

Dixon - Vaca #1

007/177 - 007/167



\*\*\*\*\*

Order	41620565	PATR/INSP 60066 DIXON-VACA #1+		
Order type	T180 EL TRANS EXPENSE RECURRING			
Status	REL DSEX NMAT PRC SETC			
User Status	UNSC			
Start date	03/01/2012			
End date	03/31/2012			
FuncLocation	ETL.6730.POLE.WOOD	60066 DIXON-VACA #1+-WOOD POLE		
Equipment	40581862	005/133 SINGLE WOOD POLE		
MaintPlanGroup	TLP	ECES		
MainWrkCenter	SACTO	Sacramento		
Priority	E	E - Schd Compl Yr 0		
MaintenancePlan				
MaintPlanItem				
Revision No.				
Partner	VLC5	JO		
Address	Conerly-Scott Veronica L.			
Phone	916/760-3344 12345			
Class	ETLEQP	Electric Transmission Line Equipment 002		
ETL_FRAMINGCONFIG	TRI POST			
ETL_UNDERBUILT	YES			
LATITUDE	38.418975000000			
LONGITUDE	-121.848324000000			
Class	ETL_POLE	ETL-POLE 002		
ETL_FRAMINGCONFIG	TRI POST			
ETL_UNDERBUILT	YES			
LATITUDE	38.418975000000			
LONGITUDE	-121.848324000000			
Operation	0004	Transmission OH Detailed Inspection		
Work center	ET_TMAN1	ELECTRIC TROUBLEMAN TRANSMISSION		
Control key	INDT	CompConf No. 16309083		
Operation key	ETL03	Milestone		
Work	12	MIN	Activity type MO	
Duration	30	DAY	Number 1	
EarlStartDate	Start time 00:00:00			
LateEndDate	End time 00:00:00			
Actual work	0	MIN	Total buffer	0 MIN

POSTED

COPY

NAME AND LAN ID OF QCR: COOPER, SXC9	
SIGNATURE OF QCR: Steve Cooper	
# OF NEW TAGS GENERATED BY QCR: 10	
SIGNATURE OF SUPERVISOR: (initials) 4/7/12 DATE	

Transmission Line Inspection Datasheet

Transmission Line Inspection Datasheet

Inspector Name :	<u>Cooper</u>	Date Inspection Completed :	<u>3-29-12</u>
Miles Inspected :	<u>16 mi</u>	# Structures Inspected :	<u>392</u>

Order : 41620565 PAIR/INSP 60066 DIXON-VACA #1+  
 Plan Group : TLP ET Poles  
 Funct Loc : ETL-6730-POLE.WOOD 60066 DIXON-VACA #1+-WOOD POLE  
 Oper Volt : 60 KV Line Miles : 16 M  
 MAT Work Center : BFZ ET\_TMAN1 Detailed Ground Inspections  
 ABC : M ELECTRIC TROUBLEMAN TRANSMISSION  
 # Struct Order : 3.92 Medium Impact ISO :

Line Last Inspected : 41611823 REAS.. DIXON-VACA #1 9/132 RPR ACCESS GA (Reassess Taos Porraine)

## Inspection Findings Data

Date Found	Structure #	Object	Damage	Priority	Comments	Est Hrs	Clearance Yes/No/Hot	Notification #
2-14-12								
3-15-12	10/18	Swl	CH07	1 year	ROTTEN POLE - OSMOSE 2000	Yes	106007910	
3-26-12	2/77	SH04	CH07	1 year	REPLACE SW59 - ARM IS ROTTEN	Yes	105999881	
2-24-12	7/176	IHO	MC10	1 year	POST INSUL OVERSTRESSED SO INSUL DAN	445	105999882	
3-23-12	AB/209	IHO	CH10	1 year	"C" TENS NEEDS BANDING TO POLE	No	105999883	
3-19-12	A9/219	Swl	MC10	1 year	REPLACE GUY STUB, RUSTY BURGS	No	105999884	
3-19-12	A9/230	Swl	MC02	1 year	BROKEN BOND WIRE	423	105999885	
3-23-12	A4/105	IHO	CH10	1 year	TORN NON-CERAMIC INSUL MIDDLE &	423	105999886	
3-23-12	A4/111	IHO	EL05	1 year	LASHED INSUL - REFRAME T-1	423	105999887	
3-23-12	A5/141	IHO	CH10	2 years	TRI PIN - REFRAME T-1	423	105999888	
3-15-12	1/42	SW04	CH07	2 years	ROTTEN X ARM	105999889		105999990

Supervisor's Initials:

11

Date Reviewed:

4/5/12

Transmission Line Inspection Datasheet

Inspector Name : Cooper Date Inspection Completed : 3-29-12  
Miles Inspected : 16 # Structures Inspected : 343

Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+  
 Plan Group : TLP ET Poles  
 Funct Loc : ETL.6730.POLE.WOOD 60066 DIXON-VACA #1+-WOOD POLE  
 Oper Volt : 60 KV Line Miles : 16 M  
 MAT Work Center : BEFZ ET\_TMAN1 Detailed Ground Inspections  
 ABC # Struct Order : 392 M ELECTRIC TROUBLEMAN TRANSMISSION  
 Medium Impact ISO :

Line Last Inspected : 41611-823 REAS- DIXON-VACA #1 M9/132 RPR ACCESS GA (Reassess Trans R-trans

## Inspection Findings Data

## COMPLETED MINOR WORK

Date Found	Structure #	Object	Damage	Priority	Comments	Test	Clearance	Notification
------------	-------------	--------	--------	----------	----------	------	-----------	--------------

2-14-12	C/1	CLEARED TREES OFF Pole & Guy
3-23-12	10/237	Dug out switch platform

October

100

Supervisor's Initials:

Date Reviewed:

# Transmission Line Object List

Inspector Name : COOPER  
 Date Inspected : 2-14-12

Funct Loc : ETL.6730.POLE.WOOD 60066 DIXON-VACA #1+-WOOD POLE  
 Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact  
 Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments # Attachment Type/Owner Listed
000/001 SINGLE WOOD POLE 40599369 TRI PIN ARM DEAD END MEDIUM EQP(AERIAL LIFT;LINE TR 38.401074000000 -121.9180960000	<input checked="" type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input checked="" type="checkbox"/> not inspctd this patrol	Total # of Attachments:  <i>* 6 conn's on jumpers</i>
000/002 SINGLE WOOD POLE 40670096 FLAT PIN ARM MEDIUM EQP(AERIAL LIFT;LINE TR 38.401678000000 -121.9173970000	<input checked="" type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input checked="" type="checkbox"/> not inspctd this patrol	Total # of Attachments:  <i>* Cleared trees off pole &amp; bugs</i>
000/003 LATTICE STEEL TOWER 40654173 DOUBLE DEAD END ANGLE MEDIUM EQP(AERIAL LIFT;LINE TR 38.402687000000 -121.9163250000	<input checked="" type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input checked="" type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 CELL-UNKNOWN 1  Notes: '02 Survey: C015607 HOST FOR 6740 2 CELL SITES OFF MERIDIAN THOUGH THE POLE YARD S/SUB
000/004 LATTICE STEEL TOWER 40576443 SUSP. STEEL DOUBLE CIR. 38.402628000000 -121.9132250000	<input checked="" type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input checked="" type="checkbox"/> not inspctd this patrol	Total # of Attachments:  Notes: '02 Survey: C015606 HOST FOR 6740
000/005 SINGLE WOOD POLE 40756286 TRI PIN ARM DEAD END 38.402611000000 -121.9116610000	<input checked="" type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input checked="" type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 <i>* Flasher Insul Compwd * Leaning guy scrub , south &amp;</i>
000/006 SINGLE WOOD POLE 40756193 TRI PIN ARM 38.402560000000 -121.9109350000	<input checked="" type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input checked="" type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1
000/007 SINGLE WOOD POLE 40814340 TRI PIN ARM <i>T-1 N/C</i> 38.402540000000 -121.9101840000	<input checked="" type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input checked="" type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1
000/008 SINGLE WOOD POLE 40813536 TRI PIN ARM 38.402552000000 -121.9094610000	<input checked="" type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input checked="" type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 <i>* Broken Tie wire</i>

# Transmission Line Object List

Page 2

Inspector Name : COOPER

Date Inspected : 2-14-12

Func Loc : ETL.6730.POLE.WOOD 60066 DIXON-VACA #1+-WOOD POLE  
 Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact

Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result [ ] completed/no problems [ ] completed/new finding(s) [ ] pre-existing cond chkd [ ] not inspctd this patrol	Attachments #
		Attachment Type/Owner Listed
000/009 SINGLE WOOD POLE 40875444 TRI PIN ARM ✓  38.402550000000 -121.9086950000	[X] completed/no problems [ ] completed/new finding(s) [ ] pre-existing cond chkd [ ] not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015601
000/010 SINGLE WOOD POLE 40865456 TRI PIN ARM ✓  38.402536000000 -121.9080000000	[X] completed/no problems [ ] completed/new finding(s) [ ] pre-existing cond chkd [ ] not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015600 MONITOR TWISTED XARM
000/011 SINGLE WOOD POLE 40612500 <b>SV(N/c)</b> ANGLE 0-30 DEGREES  38.402564000000 -121.9073370000	[X] completed/no problems [ ] completed/new finding(s) [ ] pre-existing cond chkd [ ] not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015599
000/012 SINGLE WOOD POLE 40589586 TRI PIN ARM <del>READ END</del>  38.402448000000 -121.9068350000	[X] completed/no problems [ ] completed/new finding(s) [ ] pre-existing cond chkd [ ] not inspctd this patrol	Total # of Attachments:  Notes: '02 Survey: C015598
000/013 SINGLE WOOD POLE 40695427 <b>SV(p/c)</b> ANGLE 0-30 DEGREES  38.402168000000 -121.9060440000	[X] completed/no problems [ ] completed/new finding(s) [ ] pre-existing cond chkd [ ] not inspctd this patrol	Total # of Attachments:  Notes: '02 Survey: C015597
000/014 SINGLE WOOD POLE 40665431 <del>TRI POST</del> <b>T-(N/c)</b>  38.402151000000 -121.9053110000	[X] completed/no problems [ ] completed/new finding(s) [ ] pre-existing cond chkd [ ] not inspctd this patrol	Total # of Attachments:  Notes: '02 Survey: C015596
000/015 SINGLE WOOD POLE 40768117 <del>TRI POST</del> <b>T-(N/c)</b>  38.402139000000 -121.9046210000	[X] completed/no problems [ ] completed/new finding(s) [ ] pre-existing cond chkd [ ] not inspctd this patrol	Total # of Attachments:  Notes: '02 Survey: C015595
000/016 SINGLE WOOD POLE 40767432 <del>TRIANGLE POST 70</del> <b>T-(c)</b>  38.402131000000 -121.9039190000	[X] completed/no problems [ ] completed/new finding(s) [ ] pre-existing cond chkd [ ] not inspctd this patrol	Total # of Attachments:  Notes: '02 Survey: C015594

# Transmission Line Objec. List

Page 3

Inspector Name : COOPER  
Date Inspected : 2-14-12

Funct Loc : ETL.6730.POLE.WOOD 60066 DIXON-VACA #1+-WOOD POLE  
Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact  
Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
Equip #	Attachment Type/Owner Listed	
Framing Config		
Access:		
HOST Tech ID/Equip #:		
Lat:		
Long:		
000/017 SINGLE WOOD POLE 40814342 ANGLE 0-30 DEGREES <u>(-1(c))</u> 38.402167000000 -121.9031910000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015593
000/018 SINGLE WOOD POLE 40589587 TRI PIN ARM DEAD END <u>✓</u> 38.402418000000 -121.9022720000	<input checked="" type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Pole is N/g PER OSMOSE 2008 Inspect Notes: '02 Survey: C015592
000/019 SINGLE WOOD POLE 40695277 ANGLE 0-30 DEGREES <u>SV(c)</u> 38.402488000000 -121.9016890000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C015591
000/020 SINGLE WOOD POLE 40665479 TRI POST <u>T-1 (N/C)</u> 38.402500000000 -121.9009220000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C015590
000/021 SINGLE WOOD POLE 40756288 TRI POST <u>T-1 (N/C)</u> 38.402454000000 -121.9001790000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C015589
000/022 SINGLE WOOD POLE 40767434 TRI PIN ARM <u>T-1 (N/C)</u> 38.402464000000 -121.8994480000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C015588
000/023 SINGLE WOOD POLE 40825143 TRI PIN ARM <u>DEAD END</u> <u>Team</u> 38.402490000000 -121.8987120000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C015587
000/024 SINGLE WOOD POLE 40813538 TRI PIN ARM <u>✓</u> 38.402506000000 -121.8979460000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C015586 Pole has "C" Truss

# Transmission Line Object List

Page 4

Inspector Name : COOPER

Date Inspected : 2-14-12

Funct Loc : ETL.6730.POLE.WOOD 60066 DIXON-VACA #1+-WOOD POLE  
 Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact

Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
Equip #	Attachment Type/Owner Listed	
Framing Config		
Access:		
HOST Tech ID/Equip #:		
Lat:		
Long:		
001/025 SINGLE WOOD POLE 40865994 <i>SV (u/c)</i> ANGLE 0-30 DEGREES	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1
38.402505000000 -121.8972800000	Notes: '02 Survey: C015585	
001/026 SINGLE WOOD POLE 40874335 <i>SV (u/c)</i> ANGLE 0-30 DEGREES	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1
38.402231000000 -121.8966410000	Notes: '02 Survey: C015584	
001/027 SINGLE WOOD POLE 40596147 TRI PIN ARM	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1
38.402255000000 -121.8958140000	Notes: '02 Survey: C015583	
001/028 SINGLE WOOD POLE 40599330 TRI PIN ARM	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1
38.402257000000 -121.8950880000	Notes: '02 Survey: C015582	
001/029 SINGLE WOOD POLE 40670100 TRI PIN ARM	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1
38.402254000000 -121.8942370000	Notes: '02 Survey: C015581	
001/030 SINGLE WOOD POLE 40665481 <del>TRIANGLE POST 70</del> <i>TH (c)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1
38.402239000000 -121.8935220000	Notes: '02 Survey: C015580	
001/031 SINGLE WOOD POLE 40756290 TRI PIN ARM	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1
38.402249000000 -121.8927510000	Notes: '02 Survey: C015579	
001/032 SINGLE WOOD POLE 40767436 TRI PIN ARM	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1
38.402246000000 -121.8920120000	Notes: '02 Survey: C015578	

# Transmission Line Objec. List

Page 5

Inspector Name : Cooper

Date Inspected : 2-14-12

Funct Loc : ETL.6730.POLE.WOOD 60066 DIXON-VACA #1+ -WOOD POLE  
 Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact

Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
Equip #	Attachment Type/Owner Listed	
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		
001/033 SINGLE WOOD POLE 40814344 TRI PIN ARM 38.402239000000 -121.8912530000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015577
001/034 SINGLE WOOD POLE 40823412 TRI PIN ARM 38.402240000000 -121.8904640000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015576
001/035 SINGLE WOOD POLE 40865996 TRI PIN ARM 38.402279000000 -121.8896890000	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015575
001/036 SINGLE WOOD POLE 40865458 TRIANGLE POST <del>70</del> (c) 38.402223000000 -121.8889550000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015574
001/037 SINGLE WOOD POLE 40604091 TRIANGLE POST <del>70</del> (c) 38.402219000000 -121.8881950000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015573
001/038 SINGLE WOOD POLE 40599331 TRI PIN ARM 38.402219000000 -121.8874270000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015572 MONITOR XARM Arm minor rot, "Rolled" over.
001/039 SINGLE WOOD POLE 40670104 TRI PIN ARM 38.402212000000 -121.8867270000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:  Notes: '02 Survey: C015571
001/040 SINGLE WOOD POLE 40695431 TRI PIN ARM 38.402235000000 -121.8860580000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:  Notes: '02 Survey: C015570

# Transmission Line Objec. List

Page 6

Inspector Name : Cooper

Date Inspected : 3-15-12

Funct Loc : ETL.6730.POLE.WOOD 60066 DIXON-VACA #1+-WOOD POLE  
 Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact

Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #	2-14-1
		Attachment Type/Owner Listed	
001/041 SINGLE WOOD POLE 40665433 TRI PIN ARM	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:  <i>X ARM RTN - 1yr</i>	
38.402242000000 -121.8853260000	Notes: '02 Survey: C015569		
001/042 SINGLE WOOD POLE 40756292 TRI PIN ARM	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:  <i>X ARM RTN</i>	
38.402226000000 -121.8846420000	Notes: '02 Survey: C015568 MONITOR XARM	<i>Pole Has "C" Truss</i>	
001/043 SINGLE WOOD POLE 40612506 TRI PIN ARM	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:  Notes:	
38.402199000000 -121.8839320000			
001/044 SINGLE WOOD POLE 40767438 TRI PIN ARM	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015566 MONITOR XARM	
38.402221000000 -121.8832720000			
001/045 SINGLE WOOD POLE 40825137 TRI PIN ARM	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015565	3-15-
38.402208000000 -121.8825750000			
001/046 SINGLE WOOD POLE 40813540 TRI PIN ARM	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015564	
38.4022214000000 -121.8819010000			
001/047 SINGLE WOOD POLE 40875401 TRI PIN ARM	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015563	
38.402203000000 -121.8812240000			
001/048 SINGLE WOOD POLE 40865460 TRI PIN ARM	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  <i>X ARM RTN - 1yr</i>	
38.402209000000 -121.8805520000	Notes: '02 Survey: C015562	<i>Pole Has Wood Sub</i>	

# Transmission Line Objec. List

Page 7

Inspector Name : COOPER

Date Inspected : 3-15-12

Funct Loc : ETL.6730.POLE.WOOD 60066 DIXON-VACA #1+-WOOD POLE  
 Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact

Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
001/049 SINGLE WOOD POLE 40612503 TRI PIN ARM ✓	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C015561
38.402195000000 -121.8793960000		
001/050 SINGLE WOOD POLE 40589589 TRI PIN ARM ✓	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: DIST-0310456 1 Notes: '02 Survey: C015560
38.402209000000 -121.8787730000		
001/051 SINGLE WOOD POLE 40695281 DOUBLE VERTICAL <del>DE</del> (N/C)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C015559
38.402197000000 -121.8782070000		
001/052 SINGLE WOOD POLE 40654176 TRI PIN ARM ✓	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C015558
38.401671000000 -121.8782060000		
002/053 SINGLE WOOD POLE 40768090 <del>34PFT TUNY (N/C)</del> <del>TRI PIN ARM DEAD END</del>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C015557
38.401175000000 -121.8781850000		
002/054 SINGLE WOOD POLE 40756195 TRI PIN ARM ✓	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 X ARM KUTN . 24ns Notes: '02 Survey: C015556
38.400531000000 -121.8781770000		
002/055 SINGLE WOOD POLE 40814346 TRI PIN ARM ✓	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C015555
38.399923000000 -121.8781880000		
002/056 SINGLE WOOD POLE 40823414 TRI PIN ARM ✓	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C015554
38.399307000000 -121.8781810000		

# Transmission Line Object List

Page 8

Inspector Name : COOPER

Date Inspected : 3-15-12

Funct Loc : ETL.6730.POLE.WOOD 60066 DIXON-VACA #1+-WOOD POLE  
 Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact

Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
Equip #	Attachment Type/Owner Listed	
Framing Config		
Access:		
HOST Tech ID/Equip #:		
Lat:		
Long:		
002/057 SINGLE WOOD POLE	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1
40865997 TRI PIN ARM <i>1-1 (MC)</i>		DIST-0310456 1
38.398718000000		
-121.8781740000		
Notes: '02 Survey: C015553		
002/058 SINGLE WOOD POLE	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1
40874337 TRI PIN ARM <i>✓</i>		DIST-0310456 1
38.398119000000		
-121.8781590000		
Notes: '02 Survey: C015552		
002/059 SINGLE WOOD POLE	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1
40604094 TRI PIN ARM <i>✓</i>		DIST-0310456 1
38.397494000000		
-121.8781330000		
Notes: '02 Survey: C015551		
002/060 SINGLE WOOD POLE	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1
40599371 TRI PIN ARM <i>✓</i>		DIST-0310456 1
38.396929000000		
-121.8781300000		
Notes: '02 Survey: C015550		
002/061 SINGLE WOOD POLE	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1
40670108 TRI PIN ARM <i>✓</i>		DIST-0310456 1
38.396318000000		
-121.8781470000		
Notes: '02 Survey: C015549		
002/062 SINGLE WOOD POLE	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1
40665435 TRI PIN ARM <i>✓</i>		DIST-0310456 1
38.395680000000		
-121.8781200000		
Notes: '02 Survey: C015548		
002/063 SINGLE WOOD POLE	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1
40756294 TRI PIN ARM <i>✓</i> <i>(Hc)</i>		DIST-0310456 1
38.394946000000		
-121.8781080000		
Notes: '02 Survey: C015547		
002/064 SINGLE WOOD POLE	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:
40767440 TRI PIN ARM <i>✓</i>		
38.394486000000		
-121.8781000000		
Notes: '02 Survey: C015546		

# Transmission Line Object List

Page 9

Inspector Name : COOPER

Date Inspected : 3-15-12

Funct Loc : ETL.6730.POLE.WOOD 60066 DIXON-VACA #1+-WOOD POLE  
 Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact

Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
002/065 SINGLE WOOD POLE 40825092 TRI PIN ARM T-1 (u/c)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015545
38.393876000000 -121.8780860000		
002/066 SINGLE WOOD POLE 40813542 TRI PIN ARM	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015544
38.393280000000 -121.8780890000		
002/067 SINGLE WOOD POLE 40589590 TRI PIN ARM	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015543
38.392710000000 -121.8780230000		
002/068 SINGLE WOOD POLE 40695285 TRI PIN ARM	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015542
38.392101000000 -121.8780610000		
002/069 SINGLE WOOD POLE 40654177 TRI PIN ARM	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015541 MONITOR XARM AND BRACES
38.391506000000 -121.8780300000		
002/070 SINGLE WOOD POLE 40768092 TRI PIN ARM	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015540
38.390900000000 -121.8780100000		
002/071 SINGLE WOOD POLE 40767498 TRI PIN ARM	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015539
38.390287000000 -121.8780020000		
002/072 SINGLE WOOD POLE 40825145 TRI PIN ARM	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C015538
38.389824000000 -121.8780060000		

# Transmission Line Objec. List

Page 10

Inspector Name : Cooper

Date Inspected : 3-21-12

Funct Loc : ETL.6730.POLE.WOOD 60066 DIXON-VACA #1+-WOOD POLE  
 Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact

Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #	3-15-
Equip #	Attachment Type/Owner Listed		
Framing Config			
Access:			
HOST Tech ID/Equip #:			
Lat:			
Long:			
002/073 SINGLE WOOD POLE 40823416 <del>TRIANGLE POST 70</del> <i>T-H(c)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1	
38.389067000000 -121.8779950000	Notes: '02 Survey: C015537		
002/074 SINGLE WOOD POLE 40865999 TRI PIN ARM <i>✓</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1	
38.388442000000 -121.8779930000	Notes: '02 Survey: C015536		
002/075 SINGLE WOOD POLE 40874339 <del>TRIANGLE POST 70</del> <i>T-H(c)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1	
38.387846000000 -121.8780060000	Notes: '02 Survey: C015535		
002/076 SINGLE WOOD POLE 40612561 <del>TRIANGLE POST 70</del> <i>T-H(c)</i>	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1	
38.387166000000 -121.8778960000	Notes: '02 Survey: C015534		
002/077 SINGLE WOOD POLE SW 59 40589592 FIELD SWITCH STRUCTURE	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:  <i>* Replace switch, Arm is REN.</i> <i>* Clean Vegetation</i>	
38.386637000000 -121.8778700000	Notes:		
003/078 SINGLE WOOD POLE 40657522 <i>T-(c), TPAD</i> LINE AND BUCK	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1	
38.385762000000 -121.8778300000	Notes: '02 Survey: C015532		
003/079 SINGLE WOOD POLE 40695314 TRI POST	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1	3-21-1
38.386214000000 -121.8774070000	Notes: '02 Survey: C015531		
003/080 SINGLE WOOD POLE SW 37 40586213 FIELD SWITCH STRUCTURE	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:	
38.386667000000 -121.8770440000	Notes:		

# Transmission Line Object List

Page 11

Inspector Name : Cooper

Date Inspected : 3-21-12

Funct Loc : ETL.6730.POLE.WOOD 60066 DIXON-VACA #1--WOOD POLE  
 Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact

Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
003/081 SINGLE WOOD POLE 40601228 TRI POST <i>T-1(c)</i> 38.387372000000 -121.8763700000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015529
003/082 SINGLE WOOD POLE 40874379 TRI POST <i>T-1(c)</i> 38.388151000000 -121.8757460000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015528
003/083 SINGLE WOOD POLE 40875438 TRI POST <i>T-1(c)</i> 38.388890000000 -121.8750240000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015527
003/084 SINGLE WOOD POLE 40823445 TRI POST <i>T-1(c)</i> 38.389609000000 -121.8743940000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015526
003/085 SINGLE WOOD POLE 40825104 TRI POST <i>T-1(c)</i> 38.390212000000 -121.8738830000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015525
003/086 SINGLE WOOD POLE 40752054 TRI POST <i>T-1(c)</i> 38.390847000000 -121.8733270000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015524
003/087 SINGLE WOOD POLE 40751995 TRI POST <i>T-1(c)</i> 38.391491000000 -121.8727280000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015523
003/088 SINGLE WOOD POLE 40657521 TRI POST <i>T-1(c)</i> 38.392111000000 -121.8721820000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015522

# Transmission Line Objec. List

Page 12

Inspector Name : COOPER

Date Inspected : 3-21-12

Funct Loc : ETL.6730.POLE.WOOD 60066 DIXON-VACA #1+-WOOD POLE  
 Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact

Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
Equip #	Attachment Type/Owner Listed	
Framing Config		
Access:		
HOST Tech ID/Equip #:		
Lat:		
Long:		
003/089 SINGLE WOOD POLE 40677723 TRI POST <i>T-(c)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015521
38.392619000000 -121.8716850000		
003/090 SINGLE WOOD POLE 40599373 3 HORIZONTAL POST DELTA <i>3x10 (c)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015520
38.393172000000 -121.8711650000		
003/091 SINGLE WOOD POLE 40816615 TRI POST <i>T-(c)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015519
38.393932000000 -121.8705190000		
003/092 SINGLE WOOD POLE 40825102 TRI POST <i>T-(c)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015518
38.394695000000 -121.8698910000		
003/093 SINGLE WOOD POLE 40759643 TRI POST <i>T-(c)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015517
38.395380000000 -121.8692600000		
003/094 SINGLE WOOD POLE 40768100 TRI POST <i>T-(n/c)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015516
38.396155000000 -121.8686120000		
003/095 SINGLE WOOD POLE 40657519 TRI POST <i>T-(n/c)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015515
38.396891000000 -121.8679180000		
004/096 SINGLE WOOD POLE 40695310 TRI POST <i>T-(n/c)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015514
38.397669000000 -121.8672340000		

# Transmission Line Object List

Page 13

Inspector Name : Cooper  
Date Inspected : 3-21-12

Funct Loc : ETL.6730.POLE.WOOD 60066 DIXON-VACA #1+-WOOD POLE  
Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact  
Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
004/097 SINGLE WOOD POLE 40592607 TRI POST <i>T-1(c)</i> 38.398479000000 -121.8664870000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C015513
004/098 SINGLE WOOD POLE 40612514 TRI POST <i>T-1(c)</i> 38.399158000000 -121.8659270000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C015512
004/099 SINGLE WOOD POLE 40868327 TRI POST <i>T-1(c)</i> 38.399899000000 -121.8652670000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C015511
004/100 SINGLE WOOD POLE 40875407 TRI POST <i>T-1(c)</i> 38.400633000000 -121.8646000000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C015510
004/101 SINGLE WOOD POLE 40823451 TRI POST <i>T-1(c)</i> 38.401405000000 -121.8639110000	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C015509
004/102 SINGLE WOOD POLE 40825100 TRI POST <i>T-1(c)</i> 38.402165000000 -121.8632340000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C015508 <i>BOLTS/INSULATIONS SLIGHTLY "WINGED"</i>
004/103 SINGLE WOOD POLE 40759641 TRI POST 38.402652000000 -121.8628210000	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C015507 <i>Replace Anchor - NEED to Do</i>
004/104 SINGLE WOOD POLE 40751993 TRI POST DEAD END 60 38.403296000000 -121.8622070000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C015506

# Transmission Line Object List

Page 14

Inspector Name : Cooper

Date Inspected : 3-21-12

Funct Loc : ETL.6730.POLE.WOOD 60066 DIXON-VACA #1+-WOOD POLE  
 Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact

Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
Equip #	Attachment Type/Owner Listed	
Framing Config		
Access:		
HOST Tech ID/Equip #:		
Lat:		
Long:		
004/105 SINGLE WOOD POLE	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1
40665492	DIST-0310456 1	
ERT POST	<u>T-1 (u/c)</u>	
38.403852000000		
-121.8617400000		
004/106 SINGLE WOOD POLE	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1
40695306	DIST-0310456 1	
ERT POST	<u>T-1 (u/c)</u>	
38.404413000000		
-121.8612560000		
004/107 SINGLE WOOD POLE	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1
40592606	DIST-0310456 1	
ERT POST	<u>T-1 (u/c)</u>	
38.405015000000		
-121.8607010000		
004/108 SINGLE WOOD POLE	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1
40601225	DIST-0310456 1	
ERT POST	<u>T-1 (u/c)</u>	
38.405641000000		
-121.8601850000		
004/109 SINGLE WOOD POLE	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1
40862038	DIST-0310456 1	
TRI POST DEAD END 60	<u>✓</u>	
38.406254000000		
-121.8596010000		
004/110 SINGLE WOOD POLE	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1
40875446	DIST-0310456 1	
ERT POST	<u>T-1 (c)</u>	
38.406507000000		
-121.8590040000		
004/111 SINGLE WOOD POLE	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1
40816613	DIST-0310456 1	
ANGLE 30-80 DEGREES	<u>SV (c)</u>	
38.406762000000		
-121.8583710000		
004/112 SINGLE WOOD POLE	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1
40817730	DIST-0310456 1	
ERT POST	<u>T-1 (c)</u>	
38.407313000000		
-121.8582910000		

# Transmission Line Object List

Page 15

Inspector Name : COOPER

Date Inspected : 3-28-12

Funct Loc : ETL.6730.POLE.WOOD 60066 DIXON-VACA #1+ - WOOD POLE  
 Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact

Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #	3-21-1
		Attachment Type/Owner Listed	
004/113 SINGLE WOOD POLE 40767492 <del>TRI POST DEAD END 60</del> 38.407986000000 -121.8580520000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015497	
004/114 SINGLE WOOD POLE 40768098 <del>TRI POST</del> 38.408326000000 -121.8577790000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015496	
004/115 SINGLE WOOD POLE 40665490 <del>TRI POST</del> 38.408907000000 -121.8573250000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015495	3-28-1
005/116 SINGLE WOOD POLE 40695301 <del>TRI POST</del> 38.409485000000 -121.8567670000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015494	
005/117 SINGLE WOOD POLE 40592604 <del>TRI POST</del> 38.410075000000 -121.8563170000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015493	
005/118 SINGLE WOOD POLE 40612511 <del>TRI POST</del> 38.410652000000 -121.8556850000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015492	
005/119 SINGLE WOOD POLE 40868325 <del>TRI POST</del> 38.411261000000 -121.8551380000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015491	
005/120 SINGLE WOOD POLE 40875405 <del>TRI POST</del> 38.411858000000 -121.8546320000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015490	

# Transmission Line Objec. List

Page 16

Inspector Name : Cooper

Date Inspected : 3-28-12

Funct Loc : ETL.6730.POLE.WOOD 60066 DIXON-VACA #1+ - WOOD POLE  
 Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact

Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
005/121 SINGLE WOOD POLE 40816611 <del>TRI POST</del> 38.412477000000 -121.8540850000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015489
005/122 SINGLE WOOD POLE 40825098 <del>TRI POST</del> 38.413013000000 -121.8535680000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015488
005/123 SINGLE WOOD POLE 40759639 <del>TRI POST</del> 38.413621500000 -121.8530470000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015487
005/124 SINGLE WOOD POLE 40768096 <del>TRI POST</del> 38.414230000000 -121.8525260000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015486
005/125 SINGLE WOOD POLE 40657517 <del>TRI POST</del> 38.414845000000 -121.8520120000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015485
005/126 SINGLE WOOD POLE 40695389 <del>TRI POST</del> 38.415434000000 -121.8514720000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015484
005/127 SINGLE WOOD POLE 40592603 <del>TRI POST</del> 38.416024000000 -121.8509490000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015483
005/128 SINGLE WOOD POLE 40825096 <del>TRI POST</del> 38.416632000000 -121.8503760000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015482

# Transmission Line Object List

Page 17

Inspector Name : Cooper

Date Inspected : 3-20-12

Funct Loc : ETL.6730.POLE.WOOD 60066 DIXON-VACA #1+-WOOD POLE  
 Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact

Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
Equip #	Attachment Type/Owner Listed	
Framing Config		
Access:		
HOST Tech ID/Equip #:		
Lat:		
Long:		
005/129 SINGLE WOOD POLE 40759637 TRI POST <u>T-1 (N/C)</u>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1
38.416882000000 -121.8501650000	Notes: '02 Survey: C015481	
005/130 SINGLE WOOD POLE 40759895 3 HORIZONTAL POST DELTA <u>(N/C)</u>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1
38.417218000000 -121.8498220000	Notes: '02 Survey: C015480	
005/131 SINGLE WOOD POLE 40665436 TRI POST <u>T-1 (N/C)</u>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1
38.417823000000 -121.8493060000	Notes: '02 Survey: C015479	
005/132 SINGLE WOOD POLE 40695297 TRI POST <u>T-1 (N/C)</u>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1
38.418428000000 -121.8488280000	Notes: '02 Survey: C015478	
005/133 SINGLE WOOD POLE 40581862 TRI POST <u>T-1 (N/C)</u>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1
38.418975000000 -121.8483240000	Notes: '02 Survey: C015477	
005/134 SINGLE WOOD POLE 40601222 TRI POST <u>T-1 (N/C)</u>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1
38.419612000000 -121.8477740000	Notes: '02 Survey: C015476	
005/135 SINGLE WOOD POLE 40874341 TRI POST <u>T-1 (N/C)</u>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1
38.420177000000 -121.8472060000	Notes: '02 Survey: C015475	
006/136 SINGLE WOOD POLE 40875442 TRI POST <u>T-1 (N/C)</u>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1
38.420780000000 -121.8467060000	Notes: '02 Survey: C015474	

# Transmission Line Object List

Page 18

Inspector Name : COOPER

Date Inspected : 3-20-17

Func Loc : ETL.6730.POLE.WOOD 60066 DIXON-VACA #1+-WOOD POLE  
 Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact

Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
006/137 SINGLE WOOD POLE 40809773 TRI POST <u>T-1 (N/O)</u> MEDIUM EQP(AERIAL LIFT,LINE TR 38.421367000000 -121.8461680000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015473
006/138 SINGLE WOOD POLE 40825149 TRI POST <u>T-1 (N/C)</u> 38.421969000000 -121.8456790000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015472
006/139 SINGLE WOOD POLE 40759635 TRI POST <u>T-1 (N/O)</u> 38.422537000000 -121.8451320000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015471
006/140 SINGLE WOOD POLE 40768094 TRI POST <u>T-1 (N/O)</u> 38.423136000000 -121.8445930000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015470
006/141 SINGLE WOOD POLE 40665487 TRI POST <u>T-1 (N/C)</u> 38.423730000000 -121.8440870000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015469
006/142 SINGLE WOOD POLE 40695385 TRI POST <u>T-1 (N/O)</u> 38.424297000000 -121.8435910000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015468
006/143 SINGLE WOOD POLE 40586212 TRI POST <u>T-1 (N/C)</u> 38.424904000000 -121.8430690000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015467
006/144 SINGLE WOOD POLE 40868990 SINGLE VERTICAL DEAD END <u>(N/C)</u> 38.425254000000 -121.8427550000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015466

# Transmission Line Objec. List

Page 19

Inspector Name : 3-26-12

Date Inspected : Cooper

Funct Loc : ETL.6730.POLE.WOOD 60066 DIXON-VACA #1+-WOOD POLE  
Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact

Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
006/145 SINGLE WOOD POLE 40823420 SINGLE VERTICAL DEAD END 38.425834000000 -121.8429350000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C015465
006/146 SINGLE WOOD POLE 40817728 TRI-POST 38.426481000000 -121.8423460000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C015464
006/147 SINGLE WOOD POLE 40767444 TRI-POST 38.427030000000 -121.8418360000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C015463
006/148 SINGLE WOOD POLE 40759893 TRI-POST 38.427716000000 -121.8413340000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C015462
006/149 SINGLE WOOD POLE 40657515 TRI-POST 38.428227000000 -121.8409160000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C015461
006/150 SINGLE WOOD POLE 40695381 TRI-POST 38.428784000000 -121.8403620000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C015460
006/151 SINGLE WOOD POLE 40599333 TRI-POST 38.429353000000 -121.8398050000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C015459
006/152 SINGLE WOOD POLE 40601219 TRI-POST 38.429935000000 -121.8392670000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C015458

# Transmission Line Object List

Page 20

Inspector Name : COOPER

Date Inspected : 3-26-12

Funct Loc : ETL.6730.POLE.WOOD 60066 DIXON-VACA #1+-WOOD POLE  
 Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact

Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
Equip #	Attachment Type/Owner Listed	
Framing Config		
Access:		
HOST Tech ID/Equip #:		
Lat:		
Long:		
006/153 SINGLE WOOD POLE 40868321 TRI POST <i>T-1 (N/C)</i> 38.430559000000 -121.8387840000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  <i>Replace Pole &lt;faux completed&gt;</i>
006/154 SINGLE WOOD POLE 40875403 TRI POST <i>T-1 (N/C)</i> 38.431231000000 -121.8381830000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015457
006/155 SINGLE WOOD POLE 40823418 3 HORIZONTAL POST DELTA <i>(N/C)</i> 38.431806000000 -121.8376830000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015455
007/156 SINGLE WOOD POLE 40817726 TRI POST <i>T-1 N/C</i> 38.432442000000 -121.8371800000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015454
007/157 SINGLE WOOD POLE 40767442 TRI POST <i>T-1 N/C</i> 38.432993000000 -121.8366650000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015453
007/158 SINGLE WOOD POLE 40759891 TRI POST <i>T-1 N/C</i> 38.433604000000 -121.8361000000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015452
007/159 SINGLE WOOD POLE 40665488 TRI POST <i>T-1 N/C</i> 38.434211000000 -121.8355800000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015451
007/160 SINGLE WOOD POLE 40695294 TRI POST <i>T-1 N/C</i> 38.434787000000 -121.8350810000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015450

# Transmission Line Object List

Page 21

Inspector Name : COOPER

Date Inspected : 3-24-12

Func Loc : ETL.6730.POLE.WOOD 60066 DIXON-VACA #1+-WOOD POLE  
 Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact

Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
007/161 SINGLE WOOD POLE 40592602 TRI POST 38.435348000000 -121.8345510000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015449
007/162 SINGLE WOOD POLE 40612569 TRI POST 38.435923000000 -121.8340300000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015448
007/163 SINGLE WOOD POLE 40874377 TRI POST 38.436578000000 -121.8334760000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015447
007/164 SINGLE WOOD POLE 40875434 TRI POST 38.437187000000 -121.8329210000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015446
007/165 SINGLE WOOD POLE 40816609 TRI POST 38.437740000000 -121.8324220000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015445
007/166 SINGLE WOOD POLE 40825094 TRI POST 38.438333000000 -121.8318940000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015444
007/167 SINGLE WOOD POLE 40759633 TRI POST 38.438872000000 -121.8314340000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 2 CABL-UNKNOWN 1; DIST-0310456 1  Notes: '02 Survey: C015443
007/168 SINGLE WOOD POLE 40759889 TRI POST 38.439464000000 -121.8309530000	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 3 CABL-UNKNOWN 1; DIST-0310456 1; STLT-UNKNOWN 1  Notes: '02 Survey: C015442 STREET LIGHT  <i>Insulators 248</i>

# Transmission Line Object List

Page 22

Inspector Name : Cooper

Date Inspected : 3-24-12

Funct Loc : ETL.6730.POLE.WOOD 60066 DIXON-VACA #1+-WOOD POLE  
 Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact  
 Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
007/169 SINGLE WOOD POLE 40657513 TRI POST <i>T-1 N/C</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 2 CABL-UNKNOWN 1; DIST-0310456 1  Notes: '02 Survey: C015441
38.440156000000 -121.8303120000		
007/170 SINGLE WOOD POLE 40695290 TRI POST <i>T-1 N/C</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 2 CABL-UNKNOWN 1; DIST-0310456 1  Notes: '02 Survey: C015440
38.440760000000 -121.8298060000		
007/171 SINGLE WOOD POLE 40592600 TRI POST <i>T-1 (N/C)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 2 CABL-UNKNOWN 1; DIST-0310456 1  Notes: '02 Survey: C015439
38.441296000000 -121.8292680000		
007/172 SINGLE WOOD POLE 40868319 TRI POST <i>T-1 (N/C)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 3 CABL-UNKNOWN 1; DIST-0310456 1; STLT-UNKNOWN 1  Notes: '02 Survey: C015438 STREET LIGHT
38.441931000000 -121.8287050000		
007/173 SINGLE WOOD POLE 40823449 TRI POST <i>T-1 (N/C)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 2 CABL-UNKNOWN 1; DIST-0310456 1  Notes: '02 Survey: C015437
38.442518000000 -121.8282130000		
007/174 SINGLE WOOD POLE 40816990 TRI POST <i>T-1 (N/C)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 2 CABL-UNKNOWN 1; DIST-0310456 1  Notes: '02 Survey: C015436
38.443096000000 -121.8277020000		
007/175 SINGLE WOOD POLE 40868323 TRI FIN ARM <i>T-1 (N/C)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:  Notes:
38.443866000000 -121.8272030000		
007/176 SINGLE WOOD POLE 40612509 TRI POST <i>T-1 (N/C)</i>	<input checked="" type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:  * 5 phase INSUL DAMAGED. • POST INSUL STRESSED Notes:
38.444253000000 -121.8266740000		

# Transmission Line Object List

Page 23

Inspector Name : COOPER

Date Inspected : 3-26-12

Funct Loc : ETL.6730.POLE.WOOD 60066 DIXON-VACA #1+-WOOD POLE  
 Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact

Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
007/177 SINGLE WOOD POLE 40759631 FIELD SWITCH STRUCTURE 38.444700000000 -121.8263600000	<input checked="" type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input checked="" type="checkbox"/> not inspctd this patrol	Total # of Attachments:  <i>Removed, No 7/177</i>
007/178 SINGLE WOOD POLE SW19 41137103 FIELD SWITCH STRUCTURE Sw's 17 ~ 19 38.444878000000 -121.8261090000	<input checked="" type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input checked="" type="checkbox"/> not inspctd this patrol	Total # of Attachments:  <i>REMOVED, No 7/179</i>
007/179 SINGLE WOOD POLE SW 17 40868988 TRI POST 38.444971000000 -121.8260250000	<input checked="" type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input checked="" type="checkbox"/> not inspctd this patrol	Total # of Attachments:  <i>REMOVED, No 7/179</i>
008/180 LATTICE STEEL POLE 41195902 38.445225000000 -121.8257790000	<input checked="" type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input checked="" type="checkbox"/> not inspctd this patrol	Total # of Attachments:  <i>REMOVED, No 7/180</i>
008/181 LATTICE STEEL POLE 41195901 38.445685000000 -121.8257870000	<input checked="" type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input checked="" type="checkbox"/> not inspctd this patrol	Total # of Attachments:  <i>REMOVED, No 7/181</i>
008/182 LATTICE STEEL POLE 41195916 38.446327000000 -121.8258070000	<input checked="" type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input checked="" type="checkbox"/> not inspctd this patrol	Total # of Attachments:  <i>REMOVED, No 7/182</i>
008/183 LATTICE STEEL POLE 40874397 DOUBLE VERTICAL 38.447192000000 -121.8258000000	<input checked="" type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input checked="" type="checkbox"/> not inspctd this patrol	Total # of Attachments:  <i>REMOVED, No 7/183</i>
008/184 LATTICE STEEL POLE 40868986 DOUBLE VERTICAL 38.448030000000 -121.8257780000	<input checked="" type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input checked="" type="checkbox"/> not inspctd this patrol	Total # of Attachments:  <i>REMOVED, No 7/184</i>

# Transmission Line Object List

Page 24

Inspector Name : Cooper

Date Inspected : 3-26-17

Funct Loc : ETL.6730.POLE.WOOD 60066 DIXON-VACA #1+-WOOD POLE  
 Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact

Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
008/185 LATTICE STEEL POLE 40816607 DOUBLE VERTICAL 38.448819000000 -121.8257700000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:  Notes:
008/186 LATTICE STEEL POLE 40819575 DOUBLE VERTICAL 38.449642000000 -121.8257480000	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:  Notes: <i>Replace LATTICE pole.</i>
008/187 LATTICE STEEL POLE 40767512 DOUBLE VERTICAL 38.450472000000 -121.8257190000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:  Notes:
008/188 LATTICE STEEL POLE 40768156 DOUBLE VERTICAL 38.451299000000 -121.8245910000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:  Notes:
008/189 LATTICE STEEL POLE 40665509 DOUBLE VERTICAL 38.451270000000 -121.8236970000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:  Notes:
008/190 LATTICE STEEL POLE 40681696 DOUBLE VERTICAL 38.451284000000 -121.8226480000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:  Notes: HARD ANGLE TOWER LEANS
008/191 LATTICE STEEL POLE 40592598 DOUBLE VERTICAL 38.451516000000 -121.8213130000	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:  Notes: GNGLE TOWER LEANS
008/192 LATTICE STEEL POLE 40601216 SUSPENSION (TWR) 38.451502500000 -121.8203355000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:  Notes:

# Transmission Line Object List

Page 25

Inspector Name : Cooper  
Date Inspected : 3-20-12

Funct Loc : ETL.6730.POLE.WOOD 60066 DIXON-VACA #1+-WOOD POLE  
Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact  
Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
009/193 LATTICE STEEL POLE 41195900	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:  <i>CONNECTORS</i>
38.451489000000 -121.8193580000	Notes:	
009/194 SINGLE WOOD POLE 41374066 <i>TPP</i>	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:
38.452120000000 -121.8188100000	Notes: '02 Survey: C015644	
009/195 SINGLE WOOD POLE 40823486 TRI PIN ARM ✓	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:
38.452834000000 -121.8181710000	Notes:	
009/196 SINGLE WOOD POLE 40817724 TRI PIN ARM <i>X H(0)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:
38.453320000000 -121.8177460000	Notes:	
009/197 SINGLE WOOD POLE 40759629 TRI PIN ARM <i>R-1 (v1c)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:
38.453897000000 -121.8172250000	Notes:	
009/198 SINGLE WOOD POLE 40759885 TRI PIN ARM <i>R-1 (v1c)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:
38.454429000000 -121.8167370000	Notes:	
009/199 SINGLE WOOD POLE 40665529 TRI PIN ARM ✓	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:
38.455100000000 -121.8161700000	Notes:	
009/200 SINGLE WOOD POLE 40695469 TRI PIN ARM <i>✓</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:
38.455675000000 -121.8156090000	Notes:	

# Transmission Line Object List

Page 26

Inspector Name : Cooper

Date Inspected : 3-20-12

Funct Loc : ETL.6730.POLE.WOOD 60066 DIXON-VACA #1+-WOOD POLE  
 Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact

Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
Equip #	Attachment Type/Owner Listed	
Framing Config		
Access:		
HOST Tech ID/Equip #:		
Lat:		
Long:		
009/201 SINGLE WOOD POLE 40599397 TRI PIN ARM <u>T-1 (u/c)</u>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:  <i>Notes:</i>
38.456269000000 -121.8151190000		
009/202 SINGLE WOOD POLE 40601213 TRI PIN ARM <u>✓</u>	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:  <i>Replace Pole - 24ks</i>  <i>Notes: MONITOR OLD SHELL ROTTEN POLE</i>
38.456874000000 -121.8145560000		
009/203 SINGLE WOOD POLE 40868315 TRI PIN ARM <u>T-1 (u/c)</u>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:  <i>Notes:</i>
38.457452000000 -121.8140690000		
009/204 SINGLE WOOD POLE 40875471 TRI PIN ARM <u>✓</u>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:  <i>Notes:</i>
38.457998000000 -121.8135620000		
009/205 SINGLE WOOD POLE 40823488 TRI PIN ARM <u>✓</u>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:  <i>Notes:</i>
38.458590000000 -121.8130010000		
009/206 SINGLE WOOD POLE 40817722 TRI PIN ARM <u>T-1 (u/c)</u>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:  <i>Notes:</i>
38.459287000000 -121.8124100000		
009/207 SINGLE WOOD POLE 40767514 TRI PIN ARM <u>T-1 (u/c)</u>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:  <i>Notes:</i>
38.459827000000 -121.8119320000		
009/208 SINGLE WOOD POLE 40759883 TRI PIN ARM <u>✓</u>	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:  <i>Notes: MONITOR SHELL ROTTEN POLE</i>
38.460458000000 -121.8114000000		

# Transmission Line Objec. List

Page 27

Inspector Name : Cooper  
Date Inspected : 3-20-12

Func Loc : ETL.6730.POLE.WOOD 60066 DIXON-VACA #1+-WOOD POLE Medium Impact  
Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+ Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
009/209 SINGLE WOOD POLE 4066510 TRI PIN ARM TRAMP 38.461047000000 -121.8108610000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes:
009/210 SINGLE WOOD POLE 40677719 TRI PIN ARM TRAMP 38.461632000000 -121.8103110000	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Replace X ARMS - 19n. Notes:
009/211 SINGLE WOOD POLE 40599400 TRI POST <i>T/A</i> 38.462215000000 -121.8098090000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes:
010/212 SINGLE WOOD POLE 41102751 TRI PIN ARM <i>T-1(c)</i> 38.462819000000 -121.8092750000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes:
010/213 SINGLE WOOD POLE 40695465 TRI PIN ARM <i>T-1(c)</i> 38.463378000000 -121.8087660000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes:
010/214 SINGLE WOOD POLE 40599399 TRI PIN ARM <i>T-1(c)</i> 38.464001000000 -121.8082160000	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes:
010/215 SINGLE WOOD POLE 40590224 TRI PIN ARM TRAMP <i>T-1(n/c)</i> 38.464588000000 -121.8076650000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes:
010/216 SINGLE WOOD POLE 40874399 TRI POST <i>T-1 (n/c)</i> 38.465192000000 -121.8072100000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes:

# Transmission Line Objec. List

Page 28

Inspector Name : Cooper  
Date Inspected : 3-20-12

Funct Loc : ETL.6730.POLE.WOOD 60066 DIXON-VACA #1+-WOOD POLE Medium Impact  
Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+ Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
Equip #		Attachment Type/Owner Listed
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		
010/217 SINGLE WOOD POLE 40875463 TRI POST <i>TPA</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:  Notes:
38.465775000000 -121.8066190000		
010/218 SINGLE WOOD POLE 40816605 TRI PIN ARM <i>T-1 (n/c)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:  Notes:
38.466309000000 -121.8061680000		
010/219 SINGLE WOOD POLE 40825155 TRI PIN ARM <i>T-1 (n/c)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:  Notes:
38.466777000000 -121.8057490000		
010/220 SINGLE WOOD POLE 40759627 TRI PIN ARM <i>/</i>	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:  <i>BOND WIRE Broken - 1m</i> Notes: ACROSS FROM 2010 MONTEREY
38.467110000000 -121.8054380000		
010/221 SINGLE WOOD POLE 40768153 TRI PIN ARM <i>/</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:  Notes:
38.467352000000 -121.8052370000		
010/222 SINGLE WOOD POLE 40657509 TRI PIN ARM <i>T-1(c)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:  Notes:
38.467709000000 -121.8049400000		
010/223 SINGLE WOOD POLE 40599402 TRIANGLE POST <i>T-1(c)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:  Notes:
38.468701000000 -121.8040530000		
010/224 SINGLE WOOD POLE 40601210 TRI PIN ARM <i>/</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:  Notes:
38.469233000000 -121.8035400000		

# Transmission Line Objec. List

Page 29

Inspector Name : COOPER

Date Inspected : 3-9-12

Funct Loc : ETL.6730.POLE.WOOD 60066 DIXON-VACA #1+-WOOD POLE  
 Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact

Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
Equip #	Attachment Type/Owner Listed	
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		
010/225 SINGLE WOOD POLE 40868314 <del>TRI PIN ARM</del> <i>T-1 (n/c)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:  Notes:
38.469729000000 -121.8031330000		
010/227 SINGLE WOOD POLE 40816603 TRI POST	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:  Notes:
38.470790000000 -121.8021990000		<i>Slight Pole Lean</i>
010/228 SINGLE WOOD POLE 40825161 TRI PIN ARM	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:  <i>Leaning Pole - 1qn</i> Notes:
38.471395000000 -121.8015890000		
010/229 SINGLE WOOD POLE 40761498 <del>TRI PIN ARM</del> <i>T-1 (n/c)</i>	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:  <i>Replace Pole - Pole Spotted from</i> Notes: MONITOR ROTTEN POLE
38.472008000000 -121.8010520000		
010/230 SINGLE WOOD POLE 40759881 <del>TRI PIN ARM</del> <i>T-1 (n/c)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:  Notes:
38.472609000000 -121.8005420000		
010/231 SINGLE WOOD POLE 40665513 <del>TRI POST</del> <i>T-1 (n/c)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:  Notes:
38.473129000000 -121.8000710000		
010/232 SINGLE WOOD POLE 40677715 TRI PIN ARM TRAMP <i>34RPD (n/c)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:  Notes:
38.473721000000 -121.7995520000		
010/233 SINGLE WOOD POLE 40592597 <del>TRI PIN ARM</del> <i>T-1 (n/c)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:  Notes:
38.474355000000 -121.7989750000		

# Transmission Line Objec. List

Page 30

Inspector Name : Cooper

Date Inspected : 3-23-17

Funct Loc : ETL.6730.POLE.WOOD 60066 DIXON-VACA #1+ - WOOD POLE  
 Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact

Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
Equip #	Attachment Type/Owner Listed	
Framing Config		
Access:		
HOST Tech ID/Equip #:		
Lat:		
Long:		
010/234 SINGLE WOOD POLE 40592595 TRI POST 38.474972000000 -121.7984530000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:  <i>Insulations - 2yr</i>
010/235 SINGLE WOOD POLE 40612589 TRIANGLE POST 70 T-1 (c)	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:  
010/236 SINGLE WOOD POLE 40874401 TRIANGLE POST 70 T-1 (c)	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:  Notes: Structure is FIELD SWITCH STRUCTURE No separate pole record required Deleted record 5/4/02 M. Lane 720-7105
010/237 LATTICE STEEL POLE SW 8 40868984 FIELD SWITCH STRUCTURE MEDIUM EQP(AERIAL LIFT;LINE TR 38.476174000000 -121.7973790000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:  <i>* Dug out Switch platform</i>
A006/156 SINGLE WOOD POLE 40695331 TRI POST T-1 (c)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1
A006/157 SINGLE WOOD POLE 40657532 TRI POST T-1 (c)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1
A006/158 SINGLE WOOD POLE 40768118 TRI POST T-1 (c)	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1
A006/159 SINGLE WOOD POLE 40767453 3 HORIZONTAL POST DELTA 38.344668000000 -121.9152040000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1

# Transmission Line Obj. List

Page 31

Inspector Name : COOPER  
Date Inspected : 3-23-12

Funct Loc : ETL.6730.POLE.WOOD 60066 DIXON-VACA #1+-WOOD POLE  
Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact  
Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
Equip #	Attachment Type/Owner Listed	
Framing Config		
Access:		
HOST Tech ID/Equip #:		
Lat:		
Long:		
A006/160 SINGLE WOOD POLE 40810284 TRI PIN ARM DEAD END 38.344179000000 -121.9155240000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: CONNECTIONS SHUNT guy splice 24m Notes: '02 Survey: C015697
A006/161 SINGLE WOOD POLE 40816621 TRI PIN ARM DEAD END 38.343247000000 -121.9155640000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: CONNECTIONS SHUNT guy splice 24s Notes: '02 Survey: C015698
A006/162 SINGLE WOOD POLE 40875415 TRI POST 38.342705000000 -121.9160320000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015699
A006/163 SINGLE WOOD POLE 40874371 TRI POST 38.342107000000 -121.9165690000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015700
A006/164 SINGLE WOOD POLE 40612528 TRI POST 38.341463000000 -121.9171170000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015701
A006/165 SINGLE WOOD POLE 40599337 3 HORIZONTAL POST DELTA 38.340805000000 -121.9177000000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015702
A006/166 SINGLE WOOD POLE 40660479 TRIANGLE POST 70 38.340262000000 -121.9181970000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015703
A006/167 SINGLE WOOD POLE 40665494 TRI POST 38.339644000000 -121.9187750000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes: '02 Survey: C015704

# Transmission Line Objec. List

Page 32

Inspector Name : COOPER  
Date Inspected : 3-23-12

Funct Loc : ETL.6730.POLE.WOOD 60066 DIXON-VACA #1+-WOOD POLE  
Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+ Medium Impact  
Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
Equip #	Attachment Type/Owner Listed	
Framing Config		
Access:		
HOST Tech ID/Equip #:		
Lat:		
Long:		
A006/168 SINGLE WOOD POLE 40768105 TRIANGLE POST 70 38.339026000000 -121.9192980000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:  Notes: '02 Survey: C015705
A006/169 SINGLE WOOD POLE 40767455 TRIANGLE POST 70 38.338428000000 -121.9198260000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:  Notes: '02 Survey: C015706
A006/170 SINGLE WOOD POLE 40810286 TRI POST 38.337823000000 -121.9203530000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:  Notes: '02 Survey: C015707
A007/171 SINGLE WOOD POLE 40816623 FLAT PIN ARM 38.337269000000 -121.9208650000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:  Notes: '02 Survey: C015708
A007/172 SINGLE WOOD POLE 40868998 FLAT PIN ARM 38.336639000000 -121.9214440000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:  Notes: '02 Survey: C015709  <i>Pole Has "c" Truss</i>
A007/173 SINGLE WOOD POLE 40874347 TRIANGLE POST 70 38.336229000000 -121.9218890000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:  Notes: '02 Survey: C015710  <i>Pole Has "c" Truss</i>
A007/174 SINGLE WOOD POLE 40592617 TRI POST 38.335903000000 -121.9222130000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:  Notes: '02 Survey: C015711
A007/175 SINGLE WOOD POLE 40695335 TRI POST 38.335307000000 -121.9227190000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:  Notes: '02 Survey: C015712  <i>LEANING POLE - 14K</i>

# Transmission Line Objec. List

Page 33

Inspector Name : Cooper

Date Inspected : 3-23-12

Funct Loc : ETL.6730.POLE.WOOD 60066 DIXON-VACA #1+-WOOD POLE  
 Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact

Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
Equip #	Attachment Type/Owner Listed	
Framing Config		
Access:		
HOST Tech ID/Equip #:		
Lat:		
Long:		
A007/176 SINGLE WOOD POLE 40657534 TRI POST 38.334674000000 -121.9232850000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:  <i>leaning pole</i> Notes: '02 Survey: C015713
A007/177 SINGLE WOOD POLE 40768134 TRIANGLE POST 70 38.334003000000 -121.9238110000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:  Notes: '02 Survey: C015714
A007/178 SINGLE WOOD POLE 40767494 TRIANGLE POST 70 38.333439000000 -121.9243170000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:  Notes: '02 Survey: C015715
A007/179 SINGLE WOOD POLE 40825115 TRI PIN ARM 38.332814000000 -121.9249060000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:  Notes: '02 Survey: C015716
A007/180 SINGLE WOOD POLE 40823428 TRIANGLE POST 70 38.332255000000 -121.9254450000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:  Notes: '02 Survey: C015717
A007/181 SINGLE WOOD POLE 40869000 TRI POST 38.331632000000 -121.9259590000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:  Notes: '02 Survey: C015718
A007/182 SINGLE WOOD POLE 40874349 TRIANGLE POST 70 38.331049000000 -121.9264750000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:  Notes: '02 Survey: C015719
A007/183 SINGLE WOOD POLE 40601231 TRI POST 38.330444000000 -121.9270130000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:  Notes: '02 Survey: C015720

# Transmission Line Object List

Page 34

Inspector Name : COOPER

Date Inspected : 3-23-12

Funct Loc : ETL.6730.POLE.WOOD 60066 DIXON-VACA #1+-WOOD POLE  
 Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact

Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
Equip #	Attachment Type/Owner Listed	
Framing Config		
Access:		
HOST Tech ID/Equip #:		
Lat:		
Long:		
A007/184 SINGLE WOOD POLE 40599339 TRI POST <i>T-1 (N/C)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:  Notes: '02 Survey: C015721
38.329772000000 -121.9275980000		
A007/185 SINGLE WOOD POLE 40677735 TRI POST <i>T-1 (c)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:  Notes: '02 Survey: C015722
38.329235000000 -121.9280400000		
A007/186 SINGLE WOOD POLE 40665444 TRI POST <i>T-1 (N/C)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015723
38.328649000000 -121.9285620000		
A007/187 SINGLE WOOD POLE 40759905 TRI PIN ARM <i>T</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015724
38.328046000000 -121.9291090000		
A007/188 SINGLE WOOD POLE 40767457 TRI POST <i>T-1 (c)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015725
38.327447000000 -121.9296440000		
A007/189 SINGLE WOOD POLE 40817738 TRI POST <i>T-1 (c)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015726
38.326907000000 -121.9301890000		
A007/190 SINGLE WOOD POLE 40816625 TRI POST <i>T-1 (c)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015727
38.326308000000 -121.9306600000		
A008/191 SINGLE WOOD POLE 40875417 TRI POST <i>T-1 (c)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015728
38.325700000000 -121.9311850000		

# Transmission Line Object List

Page 35

Inspector Name : COOPER  
Date Inspected : 3-23-12

Funct Loc : ETL.6730.POLE.WOOD 60066 DIXON-VACA #1+-WOOD POLE  
Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact  
Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
A008/192 SINGLE WOOD POLE 40874381 TRI POST  38.325132000000 -121.9317300000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015729
A008/193 SINGLE WOOD POLE 40612531 3 HORIZONTAL POST DELTA SHORT  38.324539000000 -121.9322460000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015730
A008/194 SINGLE WOOD POLE 40592618 TRIANGLE POST 70  38.323942000000 -121.9327330000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015731
A008/195 SINGLE WOOD POLE 40599340 TRI POST  38.323358000000 -121.9332730000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015732 MONITOR LEANING POLE
A008/196 SINGLE WOOD POLE 40695402 TRIANGLE POST 70  38.322756000000 -121.9338620000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015733
A008/197 SINGLE WOOD POLE 40665446 SPT PIN ARM <del>7-1(c)</del>  38.322439000000 -121.9340510000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015734
A008/198 SINGLE WOOD POLE 40759907 TRIANGLE POST 70  38.321868000000 -121.9345870000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015735
A008/199 SINGLE WOOD POLE 40759656 TRIANGLE POST 70  38.321282000000 -121.9351050000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015736

# Transmission Line Object List

Page 36

Inspector Name : Cooper  
Date Inspected : 2-24-12

Funct Loc : ETL.6730.POLE.WOOD 60066 DIXON-VACA #1+-WOOD POLE Medium Impact  
Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+ Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
A008/200 SINGLE WOOD POLE 40817740 TRIANGLE POST 70  38.320703000000 -121.9356300000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol  Notes: '02 Survey: C015737 MONITOR LEANING POLE ✓OK	Total # of Attachments: 1 DIST-0310456 1
A008/201 SINGLE WOOD POLE 40823466 TRIANGLE POST 70  38.320094000000 -121.9361580000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol  Notes: '02 Survey: C015738	Total # of Attachments: 1 DIST-0310456 1
A008/202 SINGLE WOOD POLE 40869002 TRIANGLE POST 70  38.319531000000 -121.9366820000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol  Notes: '02 Survey: C015739	Total # of Attachments: 1 DIST-0310456 1
A008/203 SINGLE WOOD POLE 40868337 TRIANGLE POST 70  38.318917000000 -121.9372190000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol  Notes: '02 Survey: C015740	Total # of Attachments: 1 DIST-0310456 1
A008/204 SINGLE WOOD POLE 40612534 TRIANGLE POST 70  38.318287000000 -121.9377690000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol  Notes: '02 Survey: C015741	Total # of Attachments: 1 DIST-0310456 1
A008/205 SINGLE WOOD POLE 40592620 TRIANGLE POST 70  38.317734000000 -121.9382870000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol  Notes: '02 Survey: C015742	Total # of Attachments: 1 DIST-0310456 1
A008/206 SINGLE WOOD POLE 40695339 TRIANGLE POST 70  38.317104000000 -121.9388200000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol  Notes: '02 Survey: C015743	Total # of Attachments: 1 DIST-0310456 1
A008/207 SINGLE WOOD POLE 40665483 TRIANGLE POST 70  38.316551000000 -121.9392970000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol  Notes: '02 Survey: C015744	Total # of Attachments: 1 DIST-0310456 1

# Transmission Line Objec. List

Page 37

Inspector Name : COOPER  
Date Inspected : 2-24-12

Funct Loc : ETL.6730.POLE.WOOD 60066 DIXON-VACA #1+-WOOD POLE  
Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact  
Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
A008/208 SINGLE WOOD POLE 40768107 TRIANGLE POST 70 38.316032000000 -121.9397570000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C015745
A008/209 SINGLE WOOD POLE 40759657 TRI PIN ARM 38.315651000000 -121.9401050000	<input checked="" type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 <i>*C TRUSS INSTALLED - NEEDS BANDING</i> Notes: '02 Survey: C015746
A008/210 SINGLE WOOD POLE 40825147 TRI POST 38.315217000000 -121.9404930000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C015747
A008/211 SINGLE WOOD POLE 40816627 TRI PIN ARM 38.314661000000 -121.9408950000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C015748
A008/212 SINGLE WOOD POLE 40875419 TRIANGLE POST 70 38.314173000000 -121.9413130000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C015749
A009/213 SINGLE WOOD POLE 40868339 TRIANGLE POST 70 38.313626000000 -121.9417320000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C015750
A009/214 SINGLE WOOD POLE 40612537 TRIANGLE POST 70 38.313104000000 -121.9420870000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C015751
A009/215 SINGLE WOOD POLE 40599342 TRI POST 38.312552000000 -121.9424010000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C015752

# Transmission Line Object List

Page 38

Inspector Name : Cooper

Date Inspected : 3-23-12

Funct Loc : ETL 6730 POLE WOOD 60066 DIXON-VACA #1+ WOOD POLE Medium Impact  
 Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+ Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
A009/216 SINGLE WOOD POLE 40677740 TRIANGLE POST 70  38.312031000000 -121.9427720000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015753
A009/217 SINGLE WOOD POLE 40599343 TRI POST  38.311503000000 -121.9430910000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015754
A009/218 SINGLE WOOD POLE 40677744 TRI PIN ARM  38.310894000000 -121.9434760000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015755
A009/219 SINGLE WOOD POLE 40665448 TRIANGLE POST 70  38.310244000000 -121.9438960000	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  <i>* Replace Guy Strub And Rusty Guys - X's OR/R TRACKS,</i> Notes: '02 Survey: C015756
A009/220 SINGLE WOOD POLE 40768121 3 HORIZONTAL POST DELTA SHORT  38.309584000000 -121.9440140000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015757
A009/221 SINGLE WOOD POLE 40767459 TRIANGLE POST 70  38.308845000000 -121.9444390000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015758
A009/222 SINGLE WOOD POLE 40817742 TRIANGLE POST 70  38.308387000000 -121.9447010000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015759
A009/223 SINGLE WOOD POLE 40823430 TRIANGLE POST 70  38.307611000000 -121.9451660000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015760

# Transmission Line Objec. List

Page 39

Inspector Name : COOPER  
Date Inspected : 3-23-R

Funct Loc : ETL.6730.POLE.WOOD 60066 DIXON-VACA #1+-WOOD POLE Medium Impact  
Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+ Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
Equip #	Attachment Type/Owner Listed	
Framing Config		
Access:		
HOST Tech ID/Equip #:		
Lat:		
Long:		
A009/224 SINGLE WOOD POLE 40869004 TRIANGLE POST 70 THE	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015761
38.307099000000 -121.9454710000		
A009/225 SINGLE WOOD POLE 40874351 TRIANGLE POST 70 TH(s)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015762
38.305506000000 -121.9458310000		
A009/226 SINGLE WOOD POLE 40601234 TRI PIN ARM OL	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015763
38.305791000000 -121.9462630000		
A009/227 SINGLE WOOD POLE 40599345 TRI PIN ARM	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015764
38.305094000000 -121.9466380000		
A009/228 SINGLE WOOD POLE 40677748 TRI PIN ARM	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015765
38.304493000000 -121.9470760000		
A009/229 SINGLE WOOD POLE 40650171 TRI PIN ARM T-(u/c)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015766
38.303772000000 -121.9474020000		
A009/230 SINGLE WOOD POLE 40768136 TRI PIN ARM	<input checked="" type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015767 <i>* Broken Bond</i>
38.303194000000 -121.9478390000		
A009/231 SINGLE WOOD POLE SW 19 40759659 FIELD SWITCH STRUCTURE Tarts	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:  Notes:
38.302515000000 -121.9481680000		

# Transmission Line Objec. List

Page 40

Inspector Name : COOPER

Date Inspected : 3-19-12

Funct Loc : ETL.6730.POLE.WOOD 60066 DIXON-VACA #1+-WOOD POLE  
 Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact

Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
A009/232 SINGLE WOOD POLE 40817744 ANGLE 0-30 DEGREES 38.301950000000 -121.9484710000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol  Notes: '02 Survey: C015769	Total # of Attachments: 1 DIST-0310456 1
A009/233 SINGLE WOOD POLE 40825113 TRI POST HEAVY EQP (CRANES, TRACTOR) 38.301917000000 -121.9484340000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol  Notes:	Total # of Attachments:
A03/079 SINGLE WOOD POLE 40751998 TRI PIN ARM DEAD END 38.385291000000 -121.8782050000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol  Notes: '02 Survey: C015615	Total # of Attachments: 1 DIST-0310456 1
A03/080 SINGLE WOOD POLE SW 39 40767446 TRI POST 38.384837000000 -121.8786540000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol  Notes: '02 Survey: C015617 FIELD SW STRUCTURE. NO NEED FOR INDIVIDUAL POLE RECORD. DELETED 5/7/02. S.WEEKS 720-7105	Total # of Attachments: 1 DIST-0310456 1
A03/081 SINGLE WOOD POLE 40810282 3 HORIZONTAL POST DELTA 38.384326000000 -121.8791180000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol  Notes: '02 Survey: C015618	Total # of Attachments: 1 DIST-0310456 1
A03/082 SINGLE WOOD POLE 40823422 TRI POST 38.383745000000 -121.8796190000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol  Notes: '02 Survey: C015619	Total # of Attachments: 1 DIST-0310456 1
A03/083 SINGLE WOOD POLE 40862288 TRIANGLE POST 70 38.383115000000 -121.8801650000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol  Notes: '02 Survey: C015620	Total # of Attachments: 1 DIST-0310456 1
A03/084 SINGLE WOOD POLE 40868329 TRI POST 38.382529000000 -121.8807110000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol  Notes: '02 Survey: C015621	Total # of Attachments: 1 DIST-0310456 1

Pole Has "C" Thru's

# Transmission Line Object List

Page 41

Inspector Name : COOPER

Date Inspected : 3-19-12

Funct Loc : ETL.6730.POLE.WOOD 60066 DIXON-VACA #1+-WOOD POLE  
 Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact

Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
Equip #	Attachment Type/Owner Listed	
Framing Config		
Access:		
HOST Tech ID/Equip #:		
Lat:		
Long:		
A03/085 SINGLE WOOD POLE 40590227 <del>TRI POST</del> <i>T-(c)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015622
38.381932000000 -121.8812190000		
A03/086 SINGLE WOOD POLE 40599334 <del>TRIANGLE POST 70</del> <i>T-(c)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015623
38.381322000000 -121.8817660000		
A03/087 SINGLE WOOD POLE 40695393 <del>TRI POST</del> <i>T-(c)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015624
38.380726000000 -121.8822920000		
A03/088 SINGLE WOOD POLE 40657524 TRI PIN ARM	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  <i>* Flashing Insul &gt; 1/4"</i> <i>* BKWN BOND WIRE</i>
38.380275000000 -121.8827040000		
A03/089 SINGLE WOOD POLE 40768101 <del>TRI POST</del> <i>T-(c)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015626
38.380093000000 -121.8828590000		
A03/090 SINGLE WOOD POLE 40759645 <del>TRIANGLE POST 70</del> <i>T-(c)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015627
38.379534000000 -121.8833290000		
A03/091 SINGLE WOOD POLE 40825107 <del>TRI POST</del> <i>T-(c)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015628
38.378969000000 -121.8838320000		
A03/092 SINGLE WOOD POLE 40816617 <del>TRIANGLE POST 70</del> <i>T-(c)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015629
38.378358000000 -121.8843540000		

# Transmission Line Objec. List

Page 42

Inspector Name : COOPER  
Date Inspected : 3-19-12

Funct Loc : ETL.6730.POLE.WOOD 60066 DIXON-VACA #1+ - WOOD POLE Medium Impact  
Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+ Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
Equip #	Attachment Type/Owner Listed	
Framing Config		
Access:		
HOST Tech ID/Equip #:	Notes	
Lat:		
Long:		
A03/093 SINGLE WOOD POLE 40875409 TRI PIN ARM	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015630
38.377769000000 -121.8849050000		
A03/094 SINGLE WOOD POLE 40868331 TRIANGLE POST <sup>70</sup> <i>(X) (C)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015631  <i>Pole has "C" BRUSS</i>
38.377182000000 -121.8854750000		
A03/095 SINGLE WOOD POLE 40612572 TRI POST <i>(X) (C)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015632
38.376583000000 -121.8859140000		
A03/096 SINGLE WOOD POLE 40592609 TRI PIN ARM	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  <i>X ARM - Some Rot</i> Notes: '02 Survey: C015633
38.376016000000 -121.8864740000		
A03/097 SINGLE WOOD POLE 40695318 TRI POST <i>(X) (C)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015634
38.375402000000 -121.8870000000		
A03/098 SINGLE WOOD POLE 40665439 3 HORIZONTAL POST DELTA <i>3X10 (X) (C) (THIN)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015635
38.374789000000 -121.8875670000		
A03/099 SINGLE WOOD POLE 40759897 TRI POST <i>(X) (C) (H/C)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015636
38.374187000000 -121.8881150000		
A03/100 SINGLE WOOD POLE 40759647 TRI PIN ARM <i>(X) (C) (H/C)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015637
38.373659000000 -121.8885940000		

# Transmission Line Objec. List

Page 43

Inspector Name : Cooper

Date Inspected : 3-19-12

Funct Loc : ETL.6730.POLE.WOOD 60066 DIXON-VACA #1+-WOOD POLE  
 Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact

Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
Equip #	Attachment Type/Owner Listed	
Framing Config		
Access:		
HOST Tech ID/Equip #:		
Lat:		
Long:		
A04/101 SINGLE WOOD POLE 40825109 TRI PIN ARM ✓  38.373025000000 -121.8891290000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015638
A04/102 SINGLE WOOD POLE 40823458 TRI POST ✓  38.372440000000 -121.8896660000	<input checked="" type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015639
A04/103 SINGLE WOOD POLE 40875411 TRI PIN ARM ✓  38.371860000000 -121.8901890000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015640
A04/104 SINGLE WOOD POLE 40874375 TRI POST ✓  38.371221000000 -121.8907400000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015641
A04/105 SINGLE WOOD POLE 40612520 TRIANGLE POST ✓  38.370594000000 -121.8912740000	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015642  <i>Torn N/C Insulation / Middle phase</i>
A04/106 SINGLE WOOD POLE 40592611 TRI PIN ARM ✓  38.370064000000 -121.8917380000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015643
A04/107 SINGLE WOOD POLE 40695323 TRI POST ✓  38.369446000000 -121.8922980000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015644
A04/108 SINGLE WOOD POLE 40657526 TRI POST ✓  38.369867000000 -121.8928360000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015645

# Transmission Line Object List

Page 44

Inspector Name : Cooper

Date Inspected : 3-19-12

Funct Loc : ETL.6730.POLE.WOOD 60066 DIXON-VACA #1+-WOOD POLE  
 Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact  
 Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
Equip #	Attachment Type/Owner Listed	
Framing Config		
Access:		
HOST Tech ID/Equip #:		
Lat:		
Long:		
A04/109 SINGLE WOOD POLE 40768103 TRI POST <i>T-1(c)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C015646
38.368281000000 -121.8933380000		
A04/110 SINGLE WOOD POLE 40759649 TRIANGLE POST 70 <i>T-1(c)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C015647
38.367661000000 -121.8938870000		
A04/111 SINGLE WOOD POLE 40817732 TRIANGLE POST 70	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C015648
38.367083000000 -121.8944160000	<i>* Flashed King Pin - ReFrame</i> <i>T-1 (N/C)</i>	
A04/112 SINGLE WOOD POLE 40823424 TRI PIN ARM	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: 3640 MARICOPA RD
38.366328000000 -121.8950500000		
A04/113 SINGLE WOOD POLE 40868992 TRI POST <i>T-1(c)</i>	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C015650
38.365912000000 -121.8955000000		
A04/114 SINGLE WOOD POLE 40868333 3 HORIZONTAL POST DELTA <i>3xRD (c)</i>	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C015651
38.365337000000 -121.8959450000		
A04/115 SINGLE WOOD POLE 40612523 TRI POST	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C015652
38.364708000000 -121.8964830000		
A04/116 SINGLE WOOD POLE 40599374 TRI PIN ARM	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 2 DIST-0310456 1; FIBR-UNKNOWN 1 Notes: '02 Survey: C015653
38.364465000000 -121.8967430000		

# Transmission Line Obj. List

Page 45

Inspector Name : COOPER  
Date Inspected : 3-28-12

Funct Loc : ETL.6730.POLE.WOOD 60066 DIXON-VACA #1+-WOOD POLE Medium Impact  
Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+ Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
A04/117 SINGLE WOOD POLE 40695410 TRI PIN ARM  38.364083000000 -121.8970710000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015654
A04/118 SINGLE WOOD POLE 40657528 TRI POST  38.363515000000 -121.8975790000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015655
A04/119 SINGLE WOOD POLE 40768132 TRI POST  38.363004000000 -121.8980020000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015656
A04/120 SINGLE WOOD POLE 40759651 TRI POST  38.362508000000 -121.8984030000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015657
A04/121 SINGLE WOOD POLE 40825111 TRI POST  38.361743000000 -121.8990590000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015658
A05/122 SINGLE WOOD POLE 40823460 TRI POST  38.361137000000 -121.8996910000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015659
A05/123 SINGLE WOOD POLE 40875413 TRI POST  38.360563000000 -121.9002070000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015660
A05/124 SINGLE WOOD POLE 40868335 TRI POST  38.359965000000 -121.9007350000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015661

# Transmission Line Object List

Page 46

Inspector Name : Cooper

Date Inspected : 3-28-07

Funct Loc : ETL.6730.POLE.WOOD 60066 DIXON-VACA #1+-WOOD POLE  
 Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact

Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
Equip #	Attachment Type/Owner Listed	
Framing Config		
Access:		
HOST Tech ID/Equip #:		
Lat:		
Long:		
A05/125 SINGLE WOOD POLE 40612526 TRI POST 38.359377000000 -121.9012600000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015662
A05/126 SINGLE WOOD POLE 40592612 TRI PIN ARM 38.359019000000 -121.9015620000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015663
A05/127 SINGLE WOOD POLE 40677727 TRI PIN ARM 38.358750000000 -121.9018000000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015664
A05/128 SINGLE WOOD POLE 40599336 TRI POST 38.358168000000 -121.9023190000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015665
A05/129 SINGLE WOOD POLE 40695398 TRIANGLE POST 70 38.357614000000 -121.9028010000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015666
A05/130 SINGLE WOOD POLE 40657530 TRI POST 38.356986000000 -121.9033290000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015667
A05/131 SINGLE WOOD POLE 40759899 TRI POST 38.356406000000 -121.9038340000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015668
A05/132 SINGLE WOOD POLE 40767449 3 HORIZONTAL POST DELTA MEDIUM EQP(AERIAL LIFT;LINE TR 38.355763000000 -121.9043660000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015669

# Transmission Line Objec. List

Page 47

Inspector Name : Cooper

Date Inspected : 3-28-12

Funct Loc : ETL.6730.POLE.WOOD 60066 DIXON-VACA #1+-WOOD POLE  
 Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact

Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
Equip #	Attachment Type/Owner Listed	
Framing Config		
Access:		
HOST Tech ID/Equip #:		
Lat:		
Long:		
A05/133 SINGLE WOOD POLE 40817734 TRI POST 38.355128000000 -121.9049550000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015670
A05/134 SINGLE WOOD POLE 40823426 TRI PIN ARM DEAD END 38.354627000000 -121.9054740000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1  Notes: '02 Survey: C015671  <i>Rebar (2) Anchors &amp; Connections</i> <i>rya</i>
A05/135 SINGLE WOOD POLE 40868994 TRI PIN ARM 38.354589000000 -121.9055890000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:  Notes: '02 Survey: C015672
A05/136 SINGLE WOOD POLE 40874343 TRI PIN ARM 38.354556000000 -121.9061020000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:  Notes: '02 Survey: C015673
A05/137 SINGLE WOOD POLE 40612517 DOUBLE VERTICAL 38.354506000000 -121.9063080000	<input type="checkbox"/> completed/no problems <input checked="" type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:  Notes: '02 Survey: C015674  <i>6 mous - 1yn</i> <i>INSULATIONS, &amp; Anchors</i>
A05/138 SINGLE WOOD POLE 40592614 TRI POST HEAVY EQP (CRANES, TRACTOR) 38.353994000000 -121.9067700000	<input type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input checked="" type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:  Notes: '02 Survey: C015675  <i>X LEANING POLE - 2 yrs</i>
A05/139 SINGLE WOOD POLE 40695327 TRI POST 38.353325000000 -121.9073050000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:  Notes: '02 Survey: C015676
A05/140 SINGLE WOOD POLE 40665440 TRI PIN 38.353070000000 -121.9075770000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments:  Notes: '02 Survey: C015677

# Transmission Line Objec. List

Page 48

Inspector Name : Cooper  
Date Inspected : 3-23-12

Funct Loc : ETL.6730.POLE.WOOD 60066 DIXON-VACA #1+-WOOD POLE Medium Impact  
Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+ Detailed Ground Inspections

Desc of Tech ID	Inspection Result	Attachments #
Equip #	Attachment Type/Owner Listed	
Framing Config		
Access:		
HOST Tech ID/Equip #:		
Lat:		
Long:		
A05/141 SINGLE WOOD POLE 40759901 TRI PIN ✓	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: ✓ <i>Reframe T-1</i>
38.352502000000 -121.9080900000	Notes: '02 Survey: C015678	
A05/142 SINGLE WOOD POLE 40759653 TRIANGLE POST 70	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: ✓
38.351919000000 -121.9085890000	Notes: '02 Survey: C015679	
A05/143 SINGLE WOOD POLE 40823463 TRI POST T-1 (c)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1
38.351308000000 -121.9091110000	Notes: '02 Survey: C015680	
A05/144 SINGLE WOOD POLE 40868996 TRI PIN ARM ✓	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 2 DIST-0310456 2
38.350839000000 -121.9096410000	Notes: '02 Survey: C015681	
A06/145 SINGLE WOOD POLE 40874345 TRI POST T-1 (c)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 2 DIST-0310456 2
38.350492000000 -121.9099580000	Notes: '02 Survey: C015682	
A06/146 SINGLE WOOD POLE 40612564 TRIANGLE POST 70 ✓ T-1 (c)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1
38.349922000000 -121.9103900000	Notes: '02 Survey: C015683	
<i>Post's Bases Not Plumb</i>		
A06/147 SINGLE WOOD POLE 40599385 TRIANGLE POST 70 ✓ T-1 (c)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 2 DIST-0310456 1; STLT-UNKNOWN 1
38.349676000000 -121.9106450000	Notes: '02 Survey: C015684 STREET LIGHT	
A06/148 SINGLE WOOD POLE 40677731 TRIANGLE POST 70 ✓ T-1 (c)	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1
38.349469000000 -121.9107970000	Notes: '02 Survey: C015685	

# Transmission Line Object List

Page 49

Inspector Name : COOPER  
Date Inspected : 3-28-12

Funct Loc : ETL.6730.POLE.WOOD 60066 DIXON-VACA #1+-WOOD POLE  
Order : 41620565 PATR/INSP 60066 DIXON-VACA #1+

Medium Impact  
Detailed Ground Inspections

Desc of Tech ID Equip # Framing Config Access: HOST Tech ID/Equip #: Lat: Long:	Inspection Result Notes	Attachments #
		Attachment Type/Owner Listed
A06/149 SINGLE WOOD POLE 40665443 TRIANGLE POST 70 38.349187000000 -121.9110640000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 2 DIST-0310456 1; STLT-UNKNOWN 1 Notes: '02 Survey: C015686 STREET LIGHT
A06/150 SINGLE WOOD POLE 41118543 TRIANGLE POST 70 38.348662000000 -121.9115230000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 2 DIST-0310456 1; STLT-UNKNOWN 1 Notes: '02 Survey: C015687 STREET LIGHT Equip. not in GAD
A06/151 SINGLE WOOD POLE 40759903 TRI POST 38.348359000000 -121.9117490000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C015688
A06/152 SINGLE WOOD POLE 40767451 TRIANGLE POST 70 38.348062000000 -121.9120160000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 2 DIST-0310456 1; STLT-UNKNOWN 1 Notes: '02 Survey: C015689 STREET LIGHT
A06/153 SINGLE WOOD POLE 40817736 FLAT PIN ARM 38.347757000000 -121.9122460000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C015690
A06/154 SINGLE WOOD POLE 40816619 TRI PIN ARM 38.347488000000 -121.9125080000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C015691 <i>Arm is warped</i>
A06/155 SINGLE WOOD POLE 40592615 TRI PIN ARM 38.346958000000 -121.9130400000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: 1 DIST-0310456 1 Notes: '02 Survey: C015692
B10/238 SINGLE WOOD POLE 41121537 38.477069000000 -121.7974770000	<input checked="" type="checkbox"/> completed/no problems <input type="checkbox"/> completed/new finding(s) <input type="checkbox"/> pre-existing cond chkd <input type="checkbox"/> not inspctd this patrol	Total # of Attachments: Notes:

Notification	Notif.date	Description	Description	Equipment	Function al loc.	Required End	Reference date	Order
104707180	03/01/2010	DIXON-VACA #1 0/1 RPL CONNECTORS	000/001 SINGLE WOOD POLE	40599369	ETL.6730	11/30/2015	03/01/2010	
104707187	03/01/2010	DIXON-VACA #1 0/5 RPR LEANING POLE	000/001 SINGLE WOOD POLE	40756286	ETL.6730	03/31/2013	03/01/2010	
105495624	10/06/2011	DIXON-VACA #1 00/1035 STUB POLE	000/001 SINGLE WOOD POLE	40865996	ETL.6730	10/31/2012	10/06/2011	
105251140	03/21/2011	DIXON-VACA #1 1/41 RPL XARM	000/001 SINGLE WOOD POLE	40665433	ETL.6730	03/31/2012	03/21/2011	
103749105	03/17/2009	DIXON-VACA #1 1/48 RPL XARM	000/001 SINGLE WOOD POLE	40865460	ETL.6730	03/31/2014	03/17/2009	30768564
105251145	03/21/2011	DIXON-VACA #1 2/54 RPL XARM	000/001 SINGLE WOOD POLE	40756195	ETL.6730	03/31/2012	03/21/2011	
103731034	04/14/2008	DIXON-VACA #1 2/75 IDENTIFY SPLICES	002/075 CERAMIC INSULATOR	40898765	ETL.6730	12/31/2015	04/14/2008	
102895595	01/28/2008	DIXON-VACA #1 002/076 REPLACE POLE	000/001 SINGLE WOOD POLE	40612561	ETL.6730	03/31/2013	01/28/2008	30629965
10 ~51093	12/28/2011	DIXON VACA #1 2/77 SW 59 CLEAR VEG NEED TO DO/Replace OLE SW 59	005/090 CERAMIC INSULATOR	40589592	ETL.6730	10/31/2015	12/28/2011	41630063
10.. 31035	04/14/2008	DIXON-VACA #1 3/90 IDENTIFY SPLICES	003/090 CERAMIC INSULATOR	40626015	ETL.6730	12/31/2015	04/14/2008	
103735577	04/01/2008	DIXON-VACA #1 4/99 BRIDGE BONDING	004/099 SINGLE WOOD POLE	40868327	ETL.6730	12/31/2015	04/01/2008	
103735578	04/01/2008	DIXON-VACA #1 4/100 BRIDGE BONDING	004/100 SINGLE WOOD POLE	40875407	ETL.6730	12/31/2015	04/01/2008	
103735579	04/01/2008	DIXON-VACA #1 4/101 BRIDGE BONDING	004/101 SINGLE WOOD POLE	40823451	ETL.6730	12/31/2015	04/01/2008	
103735660	04/01/2008	DIXON-VACA #1 4/102 BRIDGE BONDING	004/102 SINGLE WOOD POLE	40825100	ETL.6730	12/31/2015	04/01/2008	
104707319	03/15/2010	DIXON-VACA #1 4/103 RPL ANCHOR	NEED TO DO - 6 mos	40759641	ETL.6730	03/31/2012	03/15/2010	30870158
103735666	04/01/2008	DIXON-VACA #1 4/109 BRIDGE BONDING	004/109 SINGLE WOOD POLE	40862038	ETL.6730	12/31/2015	04/01/2008	
103735667	04/01/2008	DIXON-VACA #1 4/110 BRIDGE BONDING	004/110 SINGLE WOOD POLE	40875446	ETL.6730	12/31/2015	04/01/2008	
103735668	04/01/2008	DIXON-VACA #1 4/111 BRIDGE BONDING	004/111 SINGLE WOOD POLE	40816613	ETL.6730	12/31/2015	04/01/2008	
103735669	04/01/2008	DIXON-VACA #1 4/112 BRIDGE BONDING	004/112 SINGLE WOOD POLE	40817730	ETL.6730	12/31/2015	04/01/2008	
103731036	04/14/2008	DIXON-VACA #1 5/123 IDENTIFY SPLICES	005/123 NON-CERAMIC INSULATOR	40788977	ETL.6730	12/31/2015	04/14/2008	
103731037	04/14/2008	DIXON-VACA #1 5/127 IDENTIFY SPLICES	005/127 NON-CERAMIC INSULATOR	40618239	ETL.6730	12/31/2015	04/14/2008	
103735738	04/01/2008	DIXON-VACA #1 6/112 BRIDGE BONDING	006/112 SINGLE WOOD POLE	40876804	ETL.6730	12/31/2015	04/01/2008	
103735739	04/01/2008	DIXON-VACA #1 6/141 BRIDGE BONDING	006/141 SINGLE WOOD POLE	40665487	ETL.6730	12/31/2015	04/01/2008	
103735770	04/01/2008	DIXON-VACA #1 6/142 BRIDGE BONDING	006/142 SINGLE WOOD POLE	40695385	ETL.6730	12/31/2015	04/01/2008	
10 ~35771	04/01/2008	DIXON-VACA #1 6/143 BRIDGE BONDING	006/143 SINGLE WOOD POLE	40586212	ETL.6730	12/31/2015	04/01/2008	
10.. 35772	04/01/2008	DIXON-VACA #1 6/144 BRIDGE BONDING	006/144 SINGLE WOOD POLE	40868990	ETL.6730	12/31/2015	04/01/2008	
103735773	04/01/2008	DIXON-VACA #1 6/145 BRIDGE BONDING	006/145 SINGLE WOOD POLE	40823420	ETL.6730	12/31/2015	04/01/2008	
103735774	04/01/2008	DIXON-VACA #1 6/146 BRIDGE BONDING	006/146 SINGLE WOOD POLE	40817728	ETL.6730	12/31/2015	04/01/2008	
103735775	04/01/2008	DIXON-VACA #1 6/147 BRIDGE BONDING	006/147 SINGLE WOOD POLE	40767444	ETL.6730	12/31/2015	04/01/2008	
103735776	04/01/2008	DIXON-VACA #1 6/148 BRIDGE BONDING	006/148 SINGLE WOOD POLE	40759893	ETL.6730	12/31/2015	04/01/2008	
103735777	04/01/2008	DIXON-VACA #1 6/149 BRIDGE BONDING	006/149 SINGLE WOOD POLE	40657515	ETL.6730	12/31/2015	04/01/2008	
103735778	04/01/2008	DIXON-VACA #1 6/150 BRIDGE BONDING	006/150 SINGLE WOOD POLE	40695381	ETL.6730	12/31/2015	04/01/2008	
103735779	04/01/2008	DIXON-VACA #1 6/151 BRIDGE BONDING	006/151 SINGLE WOOD POLE	40599333	ETL.6730	12/31/2015	04/01/2008	
103735780	04/01/2008	DIXON-VACA #1 6/152 BRIDGE BONDING	006/152 SINGLE WOOD POLE	40601219	ETL.6730	12/31/2015	04/01/2008	
100485505	05/20/2002	DIXON VACA #1 6/153 REPL. POLE	000/001 SINGLE WOOD POLE	40868321	ETL.6730	03/31/2012	05/20/2002	30712513

TDV # 1

103732019	04/14/2008	DIXON-VACA #1 A6/168 IDENTIFY SPLICES	A006/168 CERAMIC INSULATOR	40799611	ETL.6730	12/31/2015	04/14/2008	
103732120	04/14/2008	DIXON-VACA #1 A6/170 IDENTIFY SPLICES	A006/170 CERAMIC INSULATOR	40837109	ETL.6730	12/31/2015	04/14/2008	
103732122	04/14/2008	DIXON-VACA #1 A7/171 IDENTIFY SPLICES	A007/171 CERAMIC INSULATOR	40842435	ETL.6730	12/31/2015	04/14/2008	
103735924	04/01/2008	DIXON-VACA #1 A7/171 BRIDGE BONDING	A007/171 SINGLE WOOD POLE	40816623	ETL.6730	12/31/2015	04/01/2008	
103732123	04/14/2008	DIXON-VACA #1 A7/174 IDENTIFY SPLICES	A007/174 CERAMIC INSULATOR	40618252	ETL.6730	12/31/2015	04/14/2008	
103732124	04/14/2008	DIXON-VACA #1 A7/175 IDENTIFY SPLICES	A007/175 CERAMIC INSULATOR	40732143	ETL.6730	12/31/2015	04/14/2008	
104707311	03/25/2010	DIXON-VACA #1 A7/175 RPR LEANING POLE	A007/175 SINGLE WOOD POLE	40695335	ETL.6730	03/31/2012	03/25/2010	
104707312	03/25/2010	DIXON-VACA #1 A7/176 RPR LEANING POLE	A007/176 SINGLE WOOD POLE	40657534	ETL.6730	03/31/2012	03/25/2010	
103732125	04/14/2008	DIXON-VACA #1 A7/178 IDENTIFY SPLICES	A007/178 CERAMIC INSULATOR	40798240	ETL.6730	12/31/2015	04/14/2008	
103732127	04/14/2008	DIXON-VACA #1 A7/179 IDENTIFY SPLICES	A007/179 CERAMIC INSULATOR	40854379	ETL.6730	12/31/2015	04/14/2008	
103732128	04/14/2008	DIXON-VACA #1 A7/181 IDENTIFY SPLICES	A007/181 CERAMIC INSULATOR	40893500	ETL.6730	12/31/2015	04/14/2008	
103732129	04/14/2008	DIXON-VACA #1 A7/182 IDENTIFY SPLICES	A007/182 CERAMIC INSULATOR	40898775	ETL.6730	12/31/2015	04/14/2008	
103732150	04/14/2008	DIXON-VACA #1 A7/183 IDENTIFY SPLICES	A007/183 CERAMIC INSULATOR	40635034	ETL.6730	12/31/2015	04/14/2008	
103732151	04/14/2008	DIXON-VACA #1 A7/185 IDENTIFY SPLICES	A007/185 CERAMIC INSULATOR	40722278	ETL.6730	12/31/2015	04/14/2008	
103732153	04/14/2008	DIXON-VACA #1 A7/186 IDENTIFY SPLICES	A007/186 CERAMIC INSULATOR	40696771	ETL.6730	12/31/2015	04/14/2008	
103732154	04/14/2008	DIXON-VACA #1 A7/190 IDENTIFY SPLICES	A007/190 CERAMIC INSULATOR	40842437	ETL.6730	12/31/2015	04/14/2008	
103732155	04/14/2008	DIXON-VACA #1 A8/191 IDENTIFY SPLICES	A008/191 CERAMIC INSULATOR	40901285	ETL.6730	12/31/2015	04/14/2008	
103732156	04/14/2008	DIXON-VACA #1 A8/192 IDENTIFY SPLICES	A008/192 CERAMIC INSULATOR	40898807	ETL.6730	12/31/2015	04/14/2008	
103732157	04/14/2008	DIXON-VACA #1 A8/194 IDENTIFY SPLICES	A008/194 CERAMIC INSULATOR	40618254	ETL.6730	12/31/2015	04/14/2008	
103735935	04/01/2008	DIXON-VACA #1 A8/196 BRIDGE BONDING	A008/196 SINGLE WOOD POLE	40695402	ETL.6730	12/31/2015	04/01/2008	
103732158	04/14/2008	DIXON-VACA #1 A8/197 IDENTIFY SPLICES	A008/197 CERAMIC INSULATOR	40696773	ETL.6730	12/31/2015	04/14/2008	
103732159	04/14/2008	DIXON-VACA #1 A8/198 IDENTIFY SPLICES	A008/198 CERAMIC INSULATOR	40790006	ETL.6730	12/31/2015	04/14/2008	
103732210	04/14/2008	DIXON-VACA #1 A8/199 IDENTIFY SPLICES	A008/199 CERAMIC INSULATOR	40788993	ETL.6730	12/31/2015	04/14/2008	
103732211	04/14/2008	DIXON-VACA #1 A8/200 IDENTIFY SPLICES	A008/200 CERAMIC INSULATOR	40845656	ETL.6730	12/31/2015	04/14/2008	
103732212	04/14/2008	DIXON-VACA #1 A8/202 IDENTIFY SPLICES	A008/202 CERAMIC INSULATOR	40893502	ETL.6730	12/31/2015	04/14/2008	
103732213	04/14/2008	DIXON-VACA #1 A8/204 IDENTIFY SPLICES	A008/204 CERAMIC INSULATOR	40639642	ETL.6730	12/31/2015	04/14/2008	
103732214	04/14/2008	DIXON-VACA #1 A8/206 IDENTIFY SPLICES	A008/206 CERAMIC INSULATOR	40732145	ETL.6730	12/31/2015	04/14/2008	
103732215	04/14/2008	DIXON-VACA #1 A8/208 IDENTIFY SPLICES	A008/208 CERAMIC INSULATOR	40799613	ETL.6730	12/31/2015	04/14/2008	
103732216	04/14/2008	DIXON-VACA #1 A8/210 IDENTIFY SPLICES	A008/210 NON-CERAMIC INSULATOR	40854411	ETL.6730	12/31/2015	04/14/2008	
103732217	04/14/2008	DIXON-VACA #1 A8/211 IDENTIFY SPLICES	A008/211 CERAMIC INSULATOR	40842439	ETL.6730	12/31/2015	04/14/2008	
103732218	04/14/2008	DIXON-VACA #1 A9/213 IDENTIFY SPLICES	A009/213 CERAMIC INSULATOR	40891332	ETL.6730	12/31/2015	04/14/2008	
103732219	04/14/2008	DIXON-VACA #1 A9/215 IDENTIFY SPLICES	A009/215 CERAMIC INSULATOR	40625986	ETL.6730	12/31/2015	04/14/2008	
103732250	04/14/2008	DIXON-VACA #1 A9/216 IDENTIFY SPLICES	A009/216 CERAMIC INSULATOR	40722280	ETL.6730	12/31/2015	04/14/2008	
103732251	04/14/2008	DIXON-VACA #1 A9/218 IDENTIFY SPLICES	A009/218 CERAMIC INSULATOR	40722282	ETL.6730	12/31/2015	04/14/2008	
103732253	04/14/2008	DIXON-VACA #1 A9/220 IDENTIFY SPLICES	A009/220 NON-CERAMIC INSULATOR	40799627	ETL.6730	12/31/2015	04/14/2008	
103732254	04/14/2008	DIXON-VACA #1 A9/222 IDENTIFY SPLICES	A009/222 CERAMIC INSULATOR	40845658	ETL.6730	12/31/2015	04/14/2008	
103732255	04/14/2008	DIXON-VACA #1 A9/224 IDENTIFY SPLICES	A009/224 CERAMIC INSULATOR	40893504	ETL.6730	12/31/2015	04/14/2008	

103735830	04/01/2008	DIXON-VACA #1 9/207 BRIDGE BONDING	009/207 SINGLE WOOD POLE	40767514	ETL6730	12/31/2015	04/01/2008	
103731555	04/14/2008	DIXON-VACA #1 9/208 IDENTIFY SPLICES	009/208 CERAMIC INSULATOR	40789986	ETL6730	12/31/2015	04/14/2008	
103735831	04/01/2008	DIXON-VACA #1 9/209 BRIDGE BONDING	009/209 SINGLE WOOD POLE	40665510	ETL6730	12/31/2015	04/01/2008	
104707316	03/18/2010	DIXON-VACA #1 9/210 RPL (2) XARMS	1 YEAR	WOOD POLE	40677719	ETL6730	03/31/2015	03/18/2010
103735832	04/01/2008	DIXON-VACA #1 9/210 BRIDGE BONDING	009/210 SINGLE WOOD POLE	40677719	ETL6730	12/31/2015	04/01/2008	
103735833	04/01/2008	DIXON-VACA #1 9/211 BRIDGE BONDING	009/211 SINGLE WOOD POLE	40599400	ETL6730	12/31/2015	04/01/2008	
103731556	04/14/2008	DIXON-VACA #1 10/212 IDENTIFY SPLICES	010/212 CERAMIC INSULATOR	41102750	ETL6730	12/31/2015	04/14/2008	
103735834	04/01/2008	DIXON-VACA #1 10/212 BRIDGE BONDING	010/212 SINGLE WOOD POLE	41102751	ETL6730	12/31/2015	04/01/2008	
103735835	04/01/2008	DIXON-VACA #1 10/213 BRIDGE BONDING	010/213 CERAMIC INSULATOR	40732210	ETL6730	12/31/2015	04/01/2008	
103735836	04/01/2008	DIXON-VACA #1 10/214 BRIDGE BONDING	010/214 SINGLE WOOD POLE	40599399	ETL6730	12/31/2015	04/01/2008	
103735837	04/01/2008	DIXON-VACA #1 10/216 IDENTIFY SPLICES	010/216 CERAMIC INSULATOR	40898827	ETL6730	12/31/2015	04/14/2008	
103735838	04/01/2008	DIXON-VACA #1 10/218 BRIDGE BONDING	010/218 SINGLE WOOD POLE	40816605	ETL6730	12/31/2015	04/01/2008	
104706902	03/18/2010	DIXON-VACA #1 10/220 RPR BOND WIRE	1 YEAR	WOOD POLE	40759627	ETL6730	03/31/2015	03/18/2010
103735839	04/01/2008	DIXON-VACA #1 10/220 BRIDGE BONDING	010/220 SINGLE WOOD POLE	40759627	ETL6730	12/31/2015	04/01/2008	
103735840	04/01/2008	DIXON-VACA #1 10/221 BRIDGE BONDING	010/221 SINGLE WOOD POLE	40768153	ETL6730	12/31/2015	04/01/2008	
103735841	04/01/2008	DIXON-VACA #1 10/222 BRIDGE BONDING	010/222 SINGLE WOOD POLE	40657509	ETL6730	12/31/2015	04/01/2008	
103735842	04/01/2008	DIXON-VACA #1 10/224 BRIDGE BONDING	010/224 SINGLE WOOD POLE	40601210	ETL6730	12/31/2015	04/01/2008	
103735843	04/01/2008	DIXON-VACA #1 10/228 BRIDGE BONDING	010/228 SINGLE WOOD POLE	40825161	ETL6730	12/31/2015	04/01/2008	
104707188	03/29/2010	DIXON-VACA #1 10/228 RPR LEANING POLE	1 YEAR	JD POLE	40825161	ETL6730	03/31/2015	03/29/2010
103731558	04/14/2008	DIXON-VACA #1 10/229 IDENTIFY SPLICES	010/229 CERAMIC INSULATOR	40791342	ETL6730	12/31/2015	04/14/2008	
103735844	04/01/2008	DIXON-VACA #1 10/229 BRIDGE BONDING	010/229 SINGLE WOOD POLE	40761498	ETL6730	12/31/2015	04/01/2008	
104714096	03/29/2010	DIXON-VACA #1 10/229 REPL POLE	1 YEAR	JD POLE	40761498	ETL6730	03/31/2015	30787048
103735845	04/01/2008	DIXON-VACA #1 10/230 BRIDGE BONDING	010/230 SINGLE WOOD POLE	40759881	ETL6730	12/31/2015	04/01/2008	
103735846	04/01/2008	DIXON-VACA #1 10/231 BRIDGE BONDING	010/231 SINGLE WOOD POLE	40665513	ETL6730	12/31/2015	04/01/2008	
103735847	04/01/2008	DIXON-VACA #1 10/232 BRIDGE BONDING	010/232 SINGLE WOOD POLE	40677715	ETL6730	12/31/2015	04/01/2008	
103735848	04/14/2008	DIXON-VACA #1 10/233 IDENTIFY SPLICES	010/233 CERAMIC INSULATOR	40618231	ETL6730	12/31/2015	04/14/2008	
103735849	04/01/2008	DIXON-VACA #1 10/233 BRIDGE BONDING	010/233 SINGLE WOOD POLE	40592597	ETL6730	12/31/2015	04/01/2008	
104707314	03/29/2010	DIXON-VACA #1 10/234 RPL INSULATORS	2 YEAR	JD POLE	40592595	ETL6730	03/31/2015	03/29/2010
103731590	04/14/2008	DIXON-VACA #1 10/236 IDENTIFY SPLICES	010/236 CERAMIC INSULATOR	40898829	ETL6730	12/31/2015	04/14/2008	
103735849	04/01/2008	DIXON-VACA #1 10/236 BRIDGE BONDING	010/236 SINGLE WOOD POLE	40874401	ETL6730	12/31/2015	04/01/2008	
104707184	03/22/2010	DIXON-VACA #1 A6/160 RPL CONNECTORS	2 1/2 years	JD POLE	40810284	ETL6730	11/30/2015	03/22/2010
104706907	03/22/2010	DIXON-VACA #1 A6/160 INSTALL SHUNT	2 1/2 years	JD POLE	40810284	ETL6730	03/31/2015	03/22/2010
104707185	03/22/2010	DIXON-VACA #1 A6/161 RPL CONNECTORS	2 1/2 years	JD POLE	40816621	ETL6730	11/30/2015	03/22/2010
104706908	03/22/2010	DIXON-VACA #1 A6/161 INSTALL SHUNT	2 1/2 years	JD POLE	40816621	ETL6730	03/31/2015	03/22/2010
103732017	04/14/2008	DIXON-VACA #1 A6/166 IDENTIFY SPLICES	A006/166 CERAMIC INSULATOR	40712661	ETL6730	12/31/2015	04/14/2008	
103732018	04/14/2008	DIXON-VACA #1 A6/167 IDENTIFY SPLICES	A006/167 CERAMIC INSULATOR	40696820	ETL6730	12/31/2015	04/14/2008	

103735782	04/01/2008	DIXON-VACA #1 7/155 BRIDGE BONDING	006/155 SINGLE WOOD POLE	40823418	ETL.6730	12/31/2015	04/01/2008	
103735783	04/01/2008	DIXON-VACA #1 7/157 BRIDGE BONDING	007/157 SINGLE WOOD POLE	40767442	ETL.6730	12/31/2015	04/01/2008	
103735784	04/01/2008	DIXON-VACA #1 7/159 BRIDGE BONDING	007/159 SINGLE WOOD POLE	40665488	ETL.6730	12/31/2015	04/01/2008	
103735785	04/01/2008	DIXON-VACA #1 7/160 BRIDGE BONDING	007/160 SINGLE WOOD POLE	40695294	ETL.6730	12/31/2015	04/01/2008	
103735786	04/01/2008	DIXON-VACA #1 7/161 BRIDGE BONDING	007/161 SINGLE WOOD POLE	40592602	ETL.6730	12/31/2015	04/01/2008	
103731038	04/14/2008	DIXON-VACA #1 7/162 IDENTIFY SPLICES	007/162 NON-CERAMIC INSULATOR	40639654	ETL.6730	12/31/2015	04/14/2008	
103735787	04/01/2008	DIXON-VACA #1 7/162 BRIDGE BONDING	007/162 SINGLE WOOD POLE	40612569	ETL.6730	12/31/2015	04/01/2008	
103735788	04/01/2008	DIXON-VACA #1 7/163 BRIDGE BONDING	007/163 SINGLE WOOD POLE	40874377	ETL.6730	12/31/2015	04/01/2008	
103735789	04/01/2008	DIXON-VACA #1 7/164 BRIDGE BONDING	007/164 SINGLE WOOD POLE	40875434	ETL.6730	12/31/2015	04/01/2008	
103735800	04/01/2008	DIXON-VACA #1 7/165 BRIDGE BONDING	007/165 SINGLE WOOD POLE	40816609	ETL.6730	12/31/2015	04/01/2008	
103735801	04/01/2008	DIXON-VACA #1 7/166 BRIDGE BONDING	007/166 SINGLE WOOD POLE	40825094	ETL.6730	12/31/2015	04/01/2008	
1. /35803	04/01/2008	DIXON-VACA #1 7/168 BRIDGE BONDING	007/168 SINGLE WOOD POLE	40759839	ETL.6730	12/31/2015	04/01/2008	
104707313	03/18/2010	DIXON-VACA #1 7/168 RPL INSULATORS	2 YEARS GOOD POLE	40759889	ETL.6730	03/31/2014	03/18/2010	
103735804	04/01/2008	DIXON-VACA #1 7/169 BRIDGE BONDING	007/169 SINGLE WOOD POLE	40657513	ETL.6730	12/31/2015	04/01/2008	
103735805	04/01/2008	DIXON-VACA #1 7/170 BRIDGE BONDING	007/170 SINGLE WOOD POLE	40695290	ETL.6730	12/31/2015	04/01/2008	
103735806	04/01/2008	DIXON-VACA #1 7/171 BRIDGE BONDING	007/171 SINGLE WOOD POLE	40592600	ETL.6730	12/31/2015	04/01/2008	
103735807	04/01/2008	DIXON-VACA #1 7/172 BRIDGE BONDING	007/172 SINGLE WOOD POLE	40868319	ETL.6730	12/31/2015	04/01/2008	
103735809	04/01/2008	DIXON-VACA #1 7/174 BRIDGE BONDING	007/174 SINGLE WOOD POLE	40816990	ETL.6730	12/31/2015	04/01/2008	
103735820	04/01/2008	DIXON-VACA #1 7/175 BRIDGE BONDING	007/175 CERAMIC INSULATOR	40891316	ETL.6730	12/31/2015	04/01/2008	
103735821	04/01/2008	DIXON-VACA #1 7/176 BRIDGE BONDING	007/176 SINGLE WOOD POLE	40612509	ETL.6730	12/31/2015	04/01/2008	
105937448	02/15/2012	DIXON-VACA #1 8/187 RPL STRUCTURE	2 YEARS EEL POLE	40767512	ETL.6730	02/28/2013	02/15/2012	
103731039	04/14/2008	DIXON-VACA #1 8/189 IDENTIFY SPLICES	008/189 CERAMIC INSULATOR	40696837	ETL.6730	12/31/2015	04/14/2008	
103735822	04/01/2008	DIXON-VACA #1 8/189 BRIDGE BONDING	008/189 LATTICE STEEL POLE	40665509	ETL.6730	12/31/2015	04/01/2008	
10373110	04/14/2008	DIXON-VACA #1 9/193 IDENTIFY SPLICES	008/193 CERAMIC INSULATOR	42572178	ETL.6730	12/31/2015	04/14/2008	
104707182	03/08/2010	DIXON-VACA #1 9/193 RPL CONNECTORS, Ø6	TEEL POLE	41195900	ETL.6730	1/30/2015	03/08/2010	
103735823	04/01/2008	DIXON-VACA #1 9/194 BRIDGE BONDING	009/194 SINGLE WOOD POLE	41374066	ETL.6730	12/31/2015	04/01/2008	
10373110	04/14/2008	DIXON-VACA #1 9/195 BRIDGE BONDING	009/195 SINGLE WOOD POLE	40823486	ETL.6730	12/31/2015	04/01/2008	
1. 35825	04/01/2008	DIXON-VACA #1 9/196 BRIDGE BONDING	009/196 SINGLE WOOD POLE	40817724	ETL.6730	12/31/2015	04/01/2008	
10373113	04/14/2008	DIXON-VACA #1 9/197 IDENTIFY SPLICES	009/197 CERAMIC INSULATOR	40788967	ETL.6730	12/31/2015	04/14/2008	
103735826	04/01/2008	DIXON-VACA #1 9/197 BRIDGE BONDING	009/197 SINGLE WOOD POLE	40759629	ETL.6730	12/31/2015	04/01/2008	
10373115	04/14/2008	DIXON-VACA #1 9/198 IDENTIFY SPLICES	009/198 CERAMIC INSULATOR	40789987	ETL.6730	12/31/2015	04/14/2008	
103731552	04/14/2008	DIXON-VACA #1 9/201 IDENTIFY SPLICES	009/201 CERAMIC INSULATOR	40626040	ETL.6730	12/31/2015	04/14/2008	
104714094	03/18/2010	DIXON-VACA #1 9/202 REFL POLE	2 YEARS JD POLE	40601213	ETL.6730	03/31/2014	03/18/2010	30787048
103735827	04/01/2008	DIXON-VACA #1 9/202 BRIDGE BONDING	009/202 SINGLE WOOD POLE	40601213	ETL.6730	12/31/2015	04/01/2008	
103735828	04/01/2008	DIXON-VACA #1 9/204 BRIDGE BONDING	009/204 SINGLE WOOD POLE	40875471	ETL.6730	12/31/2015	04/01/2008	
103731554	04/14/2008	DIXON-VACA #1 9/205 IDENTIFY SPLICES	009/205 CERAMIC INSULATOR	40850736	ETL.6730	12/31/2015	04/14/2008	
103735829	04/01/2008	DIXON-VACA #1 9/205 BRIDGE BONDING	009/205 SINGLE WOOD POLE	40823488	ETL.6730	12/31/2015	04/01/2008	

103732257	04/14/2008	DIXON-VACA #1 A9/225 IDENTIFY SPLICES	A009/225 CERAMIC INSULATOR	40898777	ETL6730	12/31/2015	04/14/2008	
103731591	04/14/2008	DIXON-VACA #1 A3/81 IDENTIFY SPLICES	A03/081 CERAMIC INSULATOR	40837105	ETL6730	12/31/2015	04/14/2008	
103731592	04/14/2008	DIXON-VACA #1 A3/82 IDENTIFY SPLICES	A03/082 CERAMIC INSULATOR	40850669	ETL6730	12/31/2015	04/14/2008	
103731593	04/14/2008	DIXON-VACA #1 A3/83 IDENTIFY SPLICES	A03/083 CERAMIC INSULATOR	40885707	ETL6730	12/31/2015	04/14/2008	
103731594	04/14/2008	DIXON-VACA #1 A3/84 IDENTIFY SPLICES	A03/084 CERAMIC INSULATOR	40891322	ETL6730	12/31/2015	04/14/2008	
103731596	04/14/2008	DIXON-VACA #1 A3/85 IDENTIFY SPLICES	A03/085 CERAMIC INSULATOR	40630559	ETL6730	12/31/2015	04/14/2008	
103731597	04/14/2008	DIXON-VACA #1 A3/87 IDENTIFY SPLICES	A03/087 CERAMIC INSULATOR	40732171	ETL6730	12/31/2015	04/14/2008	
103731598	04/14/2008	DIXON-VACA #1 A3/88 FLASHED INSUL	<del>1 YEAR</del>	40687285	ETL6730	12/31/2015	04/14/2008	
105251143	03/21/2011	DIXON-VACA #1 A3/88 RPR BOND WIRE	<del>1 YEAR</del>	40687285	ETL6730	03/31/2012	03/21/2011	
104706905	03/09/2010	DIXON-VACA #1 A3/88 RPR BOND WIRE	<del>1 YEAR</del>	40657524	ETL6730	03/09/2010		
107731599	04/14/2008	DIXON-VACA #1 A3/90 IDENTIFY SPLICES	A03/090 CERAMIC INSULATOR	40788983	ETL6730	12/31/2015	04/14/2008	
1~ , 31650	04/14/2008	DIXON-VACA #1 A3/92 IDENTIFY SPLICES	A03/092 CERAMIC INSULATOR	40842428	ETL6730	12/31/2015	04/14/2008	
103731651	04/14/2008	DIXON-VACA #1 A3/93 IDENTIFY SPLICES	A03/093 CERAMIC INSULATOR	40901278	ETL6730	12/31/2015	04/14/2008	
103731652	04/14/2008	DIXON-VACA #1 A3/96 IDENTIFY SPLICES	A03/096 CERAMIC INSULATOR	40618245	ETL6730	12/31/2015	04/14/2008	
104707317	03/09/2010	DIXON-VACA #1 A3/96 RPL XARM	<del>2 YEARS</del>	40592609	ETL6730	03/31/2012	03/09/2010	
103731653	04/14/2008	DIXON-VACA #1 A3/97 IDENTIFY SPLICES	A03/097 CERAMIC INSULATOR	40732135	ETL6730	12/31/2015	04/14/2008	
103731654	04/14/2008	DIXON-VACA #1 A3/100 IDENTIFY SPLICES	A03/100 CERAMIC INSULATOR	40788985	ETL6730	12/31/2015	04/14/2008	
103731655	04/14/2008	DIXON-VACA #1 A4/101 IDENTIFY SPLICES	A04/101 CERAMIC INSULATOR	40854373	ETL6730	12/31/2015	04/14/2008	
103731656	04/14/2008	DIXON-VACA #1 A4/103 IDENTIFY SPLICES	A04/103 CERAMIC INSULATOR	40901280	ETL6730	12/31/2015	04/14/2008	
103731657	04/14/2008	DIXON-VACA #1 A4/104 IDENTIFY SPLICES	A04/104 CERAMIC INSULATOR	40898801	ETL6730	12/31/2015	04/14/2008	
103731658	04/14/2008	DIXON-VACA #1 A4/105 IDENTIFY SPLICES	A04/105 NON-CERAMIC INSULATOR	40639637	ETL6730	12/31/2015	04/14/2008	
103731659	04/14/2008	DIXON-VACA #1 A4/107 IDENTIFY SPLICES	A04/107 CERAMIC INSULATOR	40732137	ETL6730	12/31/2015	04/14/2008	
103731690	04/14/2008	DIXON-VACA #1 A4/108 IDENTIFY SPLICES	A04/108 CERAMIC INSULATOR	40687286	ETL6730	12/31/2015	04/14/2008	
103731691	04/14/2008	DIXON-VACA #1 A4/109 IDENTIFY SPLICES	A04/109 CERAMIC INSULATOR	40799609	ETL6730	12/31/2015	04/14/2008	
103731692	04/14/2008	DIXON-VACA #1 A4/111 IDENTIFY SPLICES	A04/111 NON-CERAMIC INSULATOR	40845648	ETL6730	12/31/2015	04/14/2008	
103731693	04/14/2008	DIXON-VACA #1 A4/113 IDENTIFY SPLICES	A04/113 CERAMIC INSULATOR	40893492	ETL6730	12/31/2015	04/14/2008	
1~ , 31694	04/14/2008	DIXON-VACA #1 A4/116 IDENTIFY SPLICES	A04/116 CERAMIC INSULATOR	40626017	ETL6730	12/31/2015	04/14/2008	
103731698	04/14/2008	DIXON-VACA #1 A4/118 IDENTIFY SPLICES	A04/118 CERAMIC INSULATOR	40687289	ETL6730	12/31/2015	04/14/2008	
103731730	04/14/2008	DIXON-VACA #1 A4/119 IDENTIFY SPLICES	A04/119 CERAMIC INSULATOR	40799639	ETL6730	12/31/2015	04/14/2008	
103731731	04/14/2008	DIXON-VACA #1 A4/121 IDENTIFY SPLICES	A04/121 CERAMIC INSULATOR	40854375	ETL6730	12/31/2015	04/14/2008	
103731732	04/14/2008	DIXON-VACA #1 A5/122 IDENTIFY SPLICES	A05/122 CERAMIC INSULATOR	40850707	ETL6730	12/31/2015	04/14/2008	
103731733	04/14/2008	DIXON-VACA #1 A5/123 IDENTIFY SPLICES	A05/123 CERAMIC INSULATOR	40901281	ETL6730	12/31/2015	04/14/2008	
103731734	04/14/2008	DIXON-VACA #1 A5/124 IDENTIFY SPLICES	A05/124 CERAMIC INSULATOR	40891328	ETL6730	12/31/2015	04/14/2008	
103731735	04/14/2008	DIXON-VACA #1 A5/127 IDENTIFY SPLICES	A05/127 CERAMIC INSULATOR	40722274	ETL6730	12/31/2015	04/14/2008	
103731736	04/14/2008	DIXON-VACA #1 A5/130 IDENTIFY SPLICES	A05/130 CERAMIC INSULATOR	40687290	ETL6730	12/31/2015	04/14/2008	
103731737	04/14/2008	DIXON-VACA #1 A5/132 IDENTIFY SPLICES	A05/132 CERAMIC INSULATOR	40798196	ETL6730	12/31/2015	04/14/2008	

103731738	04/14/2008	DIXON-VACA #1 A5/134 IDENTIFY SPLICES	A05/134 CERAMIC INSULATOR	40850672	ETL.6730	12/31/2015	04/14/2008	
104707183	03/15/2010	DIXON-VACA #1 A5/134 RPL CONNECTORS	1 YEAR + 6 MONTHS - 1/4 POL	40823426	ETL.6730	11/30/2015	03/15/2010	
104707470	03/15/2010	DIXON-VACA #1 A5/134 RPL (2) ANCHORS	1 YEAR	40823426	ETL.6730	03/31/2012	03/15/2010	30870158
104707315	03/15/2010	DIXON-VACA #1 A5/137 RPL INSULATORS	6 MONTHS - 1/4 YEAR	40612517	ETL.6730	03/31/2013	03/15/2010	
103686440	03/17/2008	DIXON-VACA #1 A5/137 RPL 2 ANCHORS	6 MONTHS - 1/4 YEAR	40612517	ETL.6730	03/31/2013	03/17/2008	30870158
104707189	03/15/2010	DIXON-VACA #1 A5/138 RPR LEANING POLE	12 MONTHS - 1/2 YEARS	40592614	ETL.6730	03/31/2013	03/15/2010	
103731739	04/14/2008	DIXON-VACA #1 A6/150 IDENTIFY SPLICES	A06/150 CERAMIC INSULATOR	41118542	ETL.6730	12/31/2015	04/14/2008	
103731771	04/14/2008	DIXON-VACA #1 A6/151 IDENTIFY SPLICES	A06/151 CERAMIC INSULATOR	40790002	ETL.6730	12/31/2015	04/14/2008	
103731776	04/14/2008	DIXON-VACA #1 A6/152 IDENTIFY SPLICES	A06/152 CERAMIC INSULATOR	40798198	ETL.6730	12/31/2015	04/14/2008	
103732015	04/14/2008	DIXON-VACA #1 A6/153 IDENTIFY SPLICES	A06/153 CERAMIC INSULATOR	40845652	ETL.6730	12/31/2015	04/14/2008	
103732016	04/14/2008	DIXON-VACA #1 A6/154 IDENTIFY SPLICES	A06/154 CERAMIC INSULATOR	40842430	ETL.6730	12/31/2015	04/14/2008	

